CITY OF ALBUQUERQUE



City of Albuquerque Stormwater Construction Site Inspection Report



			PARALA	
	General Informat	ion		
Project Name and Location	RESIDENITIAL 5209			
Site Contact Name & Agency	JESSE	ESC File No.	E11E005	
Date of Inspection	1-17-18	Start/End Z	:15/3:3	
Inspector Name, COA Dept.	Stanice "Totte	n" Elliott, Stormwater Qu	ality	
Describe Present Phase of Construction	STABALIZ	ED		
Type of Inspection:				
Regular During storm	event Post-storm event (> 0.5 inc	h) 311 / Complaint Res	ponse 🗆 Follow-Up	
	Weather Informat	Market and the second		
Weather at time of this inspection	n?	Ten	nperature: ~ 42 F°	
🗆 Clear 🐧 🕻 loudy 🗆 Ra	in 🗆 Sleet 🗀 Fog 🗆 Snowing	☐ Windy	iporatare.	
Has there been a storm event sind Box 1293 Amount: 4" 14" to 34"	ce the site was Permitted? \Box Yes $\Box > \frac{3}{4}$ " \Box Snow			
	Erosion & Sediment Contro	l Inspection		
Entrance / Track-Outuquerque				
Sediment Controls / Silt Fence,				
Inlet Protection, Wattles, etc.				
1 87 10 3				
STAC	BACIZED/			
w.cabq.gov				
Erosion Controls Housekeeping/Pollutant Controls				
Debris/Pollutants/Sediment in MS Notes	64		•	
ls site being maintained in compliance v	vith the Drainage Ordinance (1979) Yes No	A. L. Clepin Signature	1-17-18 Date	

ECS File: EUEOOS



City of Albuquerque Stormwater Construction Site Inspection Report

	General Informatio	on		
Project Name and Location	5209 Montano Plage			
Site Contact Name & Agency	Jesse	Contact Phone E-mail	#/	
Date of Inspection	6-29-17	Start/End Time	25/2:05	
Inspector Name, COA Dept.	Curtis Che	rne, Stormwater Qualit	y	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	House weather in			
Type of Inspection:			<i>(</i> 2)	
Regular	m event • Post-storm event (> 0.5 inch)	• 311 / Complaint Re	esponse • Follow-Up	
	Weather Informatio	on		
Weather at time of this inspection of the control o	ion? Rain · Sleet · Fog · Snowing		emperature: ~ / D & F°	
Has there been a storm event si Amount: < 1/4" to 3/4" to 3/4"				
	Erosion & Sediment Control	Inspection		
Entrance / Track-OutSediment Controls / Silt Formula	ence,			
Check Dams, Waddles,	etc. walls			
 Erosion Controls / Mulch, 	Seed, ~O			
Housekeeping/Pollutant Co.	ontrols Ok			
• Debris/Pollutants/Sedimen	it in MS4			
Notes Clean	up but in street	av an Sd	w/c	
Is site being maintained in compliance	ce with the Drainage Ordinance ? Yes No	Signature	Ch 6-29-17 Date	

ECS File: Eu Edds



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information			
Project Name and Location	Residentral 5209 Merkeno pla	Fa		
Site Contact Name & Agency	7	Contact Phone #/ E-mail		
Date of Inspection	6-16-17	Start/End //:06		
Inspector Name, COA Dept.	Curtis Che	rne, Stormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	houce insheal			
	Weather Information? Rain · Sleet · Fog · Snowing ince the site was Permitted? · Yes	Temperature: ~ 96 F° • Windy • No		
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles Erosion Controls / Mulch Housekeeping/Pollutant C Debris/Pollutants/Sedime Notes	Controls 01			
Is site being maintained in complian	nce with the Drainage Ordinance?" Yes	Signature Date		

Cherne, Curtis			
Sent: Friday, J To: Cherne,			
Subject: Re: 5209	9 Montano Plaza COnsturciton site inspection		
contacted my grading contractor t	d me and reported to me these violations. I am at the house now and have o getvthis cleaned up. It will be resolved before the end of the day on e. I apologize for the oversight on my part.		
Jesse W. Deubel (505) 440-2621			
On Jun 16, 2017 1:52 PM, "Cherr	ne, Curtis" < CCherne@cabq.gov> wrote:		
Jesse,			
Good afternoon.			
I stopped by the project today.			
The following issues were observ	ed:		
1. Sediment in gutter in cul-de-sa	ic.		
2. Use of dirt ramp to access site	·.		
3. Sediment on sidewalk.			
4. Sediment in Montano Plaza down to Dellyne Ave.			
	the street, gutter and the sidewalk in the cul-de-sac and from the gutter in Ave. The City is trying to keep sediment out of the storm drains and the r		
Standard mitigation time is seven	days.		
Thanks.			
Curtis Cherne, PE, QCIS			

Principal Engineer

Stormwater Quality

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Friday, June 16, 2017 1:52 PM

To:

'jesse.deubel@gmail.com'

Subject: Attachments: 5209 Montano Plaza COnsturciton site inspection dirt_ramp.jpg; Montano_plaza.jpg; sediment_gutter.jpg

Jesse,

Good afternoon.

I stopped by the project today.

The following issues were observed:

- 1. Sediment in gutter in cul-de-sac.
- 2. Use of dirt ramp to access site.
- 3. Sediment on sidewalk.
- 4. Sediment in Montano Plaza down to Dellyne Ave.

Please remove all sediment from the street, gutter and the sidewalk in the cul-de-sac and from the gutter in Montano Plaza down to Dellyne Ave. The City is trying to keep sediment out of the storm drains and the river. Standard mitigation time is seven days.

Thanks.

Curtis Cherne, PE, QCIS Principal Engineer Stormwater Quality COA 505-924-3420

303-924-3420

[&]quot;Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."