



City of Albuquerque
Stormwater Construction Site
Inspection Report

General Information

Project Name and Location	JDP Family DKD Storage Facility 3605 Osuna Rd. N.E. ABQ, N.M.		
Site Contact Name & Agency	Josué Ayala 505.269.7333 Ayala Const. Corp. (G.C.)	ESC File No. NPDES ID No.	
Date of Inspection	11.21.19	Start/End Time	1-2 pm
COA Inspector Name	Curtis Cherne, Stormwater Quality		
Describe Present Phase of Construction	concrete phase / Footings / Foundation		
Type of Inspection:	BMP Inspection Soch Inspection berm inspection		

Weather Information

Weather at time of this inspection?

just finished raining

Has there been a storm event since the site was Permitted?

Amount:

Rain

Inspection

CGP	BMP / Activity	Maintenance Required? (1)	Corrective Action Required? (2)	Location and Notes
1.5	checked			
2.2.1	berms	no		built for footings but kept all H ₂ O on site.
2.2.3	checked			
2.2.3	soch	no		Soch was staked throughout fence / surrounding perimeter
2.2.3	checked			fence. Stayed in place and
2.2.3	pond	no		kept water and debris inside
2.2.3				property footprint.

pond had little H₂O but kept all H₂O from run off.