



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name and Location	Homewood Suites Addition 5400 San Antonio NE		
Site Contact Name & Agency	Finnoff, Vinny Perumal Ken-Gc Mountain West Logging	ESC File No.	E18E050
		NPDES ID No.	NMR100158
Date of Inspection	12-12-18	Start/End Time	10:10/10:50
COA Inspector Name	Curtis Cherne, Stormwater Quality		
Describe Present Phase of Construction	1st story framed		
Type of Inspection:			
<input checked="" type="radio"/> Regular <input type="radio"/> During storm event <input type="radio"/> Post-storm event (> 0.25 inch) <input type="radio"/> 311 / Complaint Response <input type="radio"/> Follow-Up			

Weather Information

Weather at time of this inspection? Temperature: ~ 35 F°

Clear
 Cloudy
 Rain
 Sleet
 Fog
 Snowing
 Windy

Has there been a storm event since the site was Permitted? Yes No

Amount:
 < 1/4"
 1/4" to 3/4"
 > 3/4"
 Snow _____"

Inspection

CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes
1.5	Post a Notice		
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft		
2.2.3	Sediment control along any perimeter	✓	missing sediment BMP south side
2.2.3	Sediment control along any perimeter		Look to berm 8-12" high compacted east 2/3 silt surface west 1/3
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track-out		

2.2.5	Manage stockpiles		
2.2.6	Minimize Dust		
2.2.10	Protect Storm Drain Inlets		
2.2.10	Protect Storm Drain Inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.3.1	Equipment and Vehicle Fueling		
2.3.2	Equipment and Vehicle Washing		
2.3.3	Building Material Storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and Domestic Wastes	✓	Debris pile not in container
2.3.3	Construction and Domestic Wastes	✓	no waste container on site full
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site?	• Yes • No	
4	Self-Inspection Reports		Latest Report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within 7 days.

Notes:

hydromulched area south of channel

KEN WILT KWILT76@GMAIL.COM

505-710-5570

Section of construction fence or wall of channel

City of Albuquerque Stormwater Inspector Signature and Date: Curtis C Cherne 12-12-18

Signature Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov