

## City of Albuquerque Stormwater Construction Site Inspection Report

	MELLIN		General Ir	formation			
ESC File No.	C File No. E19D025		25C2 Project Name:		Good 2 Go Store #333 Demolition		
NPDES Id. No.	N//		ocation:		7330 San Antonio Dr. NE		
		Owner		Contractor			
Operator		La Cueva Property, LLC			Emergency Environmental Services		
Contact name & title		Mike Petersen			Dan Kelley		
e-mail		mike.petersen@southforkmanagemen			dank@emergencyenv.com		
Contact Phone #					505-503-3884		
COA Inspector		Thomas Evans			Start/End Time:	1:00 PM-1:10 PM	
Construction Phase:					noliton		
Type of Inspection:		Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint Foll	ow Up
Weathe	er at time of i	nspection? cloudy			Temperature: ~ 78		
Estimated date of last storm 0.25" or greater 6/29/2021							
ltone							
Item	Deficiency/ Corrective Action						
Number							
1	No posting of ESC Permit. Post ESC permit in a location clearly visible to the public.						
2	Wattles did not cover entire southern boundary. Crew placed wattles during inspection.						
3	Silt fence not towed at SW corner. Properly tow in silt fence.						
4							
5							
			I				
2.1	Discharge off site?	(Y/N)	no				
		ion Reports	Requested			None on file	

Notes: Building was approximately 95% demolished. Rolloff trucks were on site to haul debris. Spoke with crew member to install wattles and maintain the silt fence.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Thomas Evans (505-803-6215) tevans@cabq.gov

Thomas Evans 06/29/2021