

Cherne, Curtis

FL1D010

From: Cherne, Curtis
Sent: Friday, September 04, 2015 9:04 AM
To: nancybelen25@yahoo.com; 'davisbelen@aol.com'
Subject: erosion at Vista De La Luz

Nancy/Jerry,
Good morning.

I checked the grading plan and the slopes of the hill were 3 horizontal to 1 vertical. The engineer certified this after the grading was complete. This meets the minimum City criteria wherein slope (erosion) protection is not required.


So our discussion on this being a design problem and the responsibility of the engineer is less valid and the City will not be able to approach the engineer stating their design was below standards.

I will still show the pictures and describe the situation to the City Engineer and get back with you.

Curtis

See photos in share drive

4-2-15



Ditch 1/2 m @ 0.5 m

Part 1 hole 2.5 @ 0.5 m

due to slope

50

V
&
A

Should you have any questions or if we may be of further service, please do not hesitate to call.

Sincerely,
Vinyard & Associates, Inc.



Martin D. Vinyard, PE

V

