

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Nar	ne:	ABQ North	Storage					
Location:		5124 2nd Street						
Site Contact Name &		David Murphy - THS Construction ESC File N			F15E052E			
		ths0323@		NPDES Id. No.		NMR1001E4		
Agency				00/1015hrs		MMMTOOTL4		
Inspection Date: CoA Stormwater Inspecto		05/29/19		00/10131118				
		r:	Timothy E. Sims					
Construction Phase:			1	T		T	1	
Type of Inspection:		Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint x	Follow Up	
Weath	er at time of i	nspection?	Clea	ır	Tempe	erature: ~	63*	
Estimated	date of last s	torm 0.25" or greater			5/11/2019			
14								
Item	Deficiency/ Corrective Action							
Number	,,							
	no issues notedThis site has not provided a self-inspection report. Provide report.							
	no issues noted. This site has not provided a sentinspection report.							
2.1	Discharge off site?	(Y/N)	No					
	_							
4	Self Inspect	tion Report	s requested	Latest rep	ort Date:	5/1/20	19	
							•	
NI . I .								
Notes:								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

05/29/19_____