



## City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
Project Name:	Top Golf				
Location:	1600 Desert Surf				
Site Contact Name & Agency	Richard Breck/ Troy Manwill - Arco	ESC File No.	F16E003E1		
	<a href="mailto:rbreck@arc01.com">rbreck@arc01.com</a>	NPDES Id. No.	NMR100XF		
Inspection Date:	09/30/19	Start/End Time:	0900/1100hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	C&G, site work				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	75*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action
1	Please provide latest SWPPP self-inspection report
2	Silt fence maintenance is required on silt fence on the perimeter adjacent to the pond requires maintenance. Please mitigate.
3	Massive amounts of sediment in the streets, Desert Surf Circle from Alexander back to Alexander & the access aisle from Desert Surf Circle to the top of the hill (Montano) requires sediment mitigation.
4	Too much erosion is reflected at and around the pond. The slopes are showing signs of erosion also. These slopes are required to be regraded and stabilized.
5	The inlets in Desert Surf Circle requires inlet protection. Please provide inlet protection.
6	Perimeter silt fence has sediment build up that exceeds 50% of silt fence height. Please remove build up on silt fence.
2.1	Discharge off site? (Y/N)      No
4	Self Inspection Reports      requested      Latest report Date:      9/23/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:      Timothy E. Sims - (505) 803-6155

[tsims@cabq.gov](mailto:tsims@cabq.gov)      09/30/19