

## City of Albuquerque Stormwater Construction Site Inspection Report

			General In	formation		
Project Name:		Top Golf				
Location:		1600 Desert Surf				
Site Contact Name &			roy Manwill - Arco			F16E003E1
Agency		rbreck@arc01.com NPDES Id. No.			NMR100XF	
Inspection				00/1100hrs		
	water Inspecto	r: Tii	mothy E. Sims			
	ction Phase:	vertical  Regular   Storm Event   Post Storm Event > 0.25"   311/Complaint x Follow Up				
Type of If	spection:	Regular	Storm Event	Post Storm E	vent >0.25	311/Complaint x Follow Up
Weather at time of inspection? Clear Temperature: ~ 51*						
Estimated date of last storm 0.25" or greater 10/4/2019						
Item	Deficiency/ Corrective Action					
Number						
1	Please provide latest SWPPP self-inspection report.					
2	A construction entrance or equal BMP is required for the access point to the ponding area.					
	Signs of track out are in Desert Surf.					
3	Please remove sediment in Desert Surf					
4	Maintenance is required for the refuse container. Please provide the ability to cover refuse					
	container.					
5	Sediment in the cut through roadway requires mitigation. The northern most track out pad may					
	require lengthing to prevent track out. Also sediment collection points in the parking areas					
	also require m	itigation.				
6	Construction and domestic waste not in acceptable container. Please train/ ensure trades utilize					
	provided refuse container.					
			Ī	1		
2.1	Discharge off site?	(Y/N)	No		T	
4	Self Inspect	tion Reports	requested	Latest rep	ort Date:	9/23/2019
Notes:						

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

10/22/19