

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:		Top Golf							
Location:		1600 Desert Surf							
Site Contact Name &		Troy Manwill - Arco Murray ESC File No. F16E003E1							
Agency		troymanwill@arcomurray.com NPDES Id. No. NMR100XF							
Inspection Date:				0835/0915					
	water Inspector								
	ction Phase:	vertical Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up							
Type of Ir	nspection: <u>x</u>	Regular	Storm Event	Post Storm	event >0.25	311/Complaint	Follow Up		
Weath	er at time of i	nspection?	Clea	ar	Tempe	rature: ~	28*		
Weather at time of i Estimated date of last s		torm 0.25"	or greater			11/27/2019			
Item			_						
Number			Deficienc	cy/ Correctiv	e Action				
1	Cadiment DND needed for Dand let								
	Sediment BMP needed for Pond lot.								
2	Northern most trackout pad requires mitigation.								
3	Restore silt fence where landscapers are working.								
2.1	Discharge off site?	(Y/N)	No						
4	Self Inspect	tion Reports	-	Latest rep	oort Date:	12/19/2	019		
	-			-					

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155