

City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation			
Project Nar	ne:	Tru by Hilton					
Location:		4949 Jefferson NE					
Site Contact Name &		Ken Moore, Wright Hospitality ESC File No. F17E044C					
Agency		ken@wrigh		ospitality.com NPDES Id. No. NMR10021J			
Inspection Date:				55/1015hrs			
	water Inspector	r:	Timothy E. Sims				
Construction Phase: vertical							
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up							
144 .1				-			0.6%
Weath	er at time of i	nspection?	Clea	r	Temper	rature: ~	36*
Estimated	date of last s	torm 0.25	or greater		11/27/2019		
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	Track out pad requires maintenance						
2	Perimeter BMP's require maintenance. Please re-establish sediment BMP's.						
3	Inlet protection is required for onsite inlets.						
4	Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would						
	mitigate wind blown remnants.						
5	Several washout on site require mitigation (see photos)						
6	Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19						
1/2/2020							
1	Waste not in acceptable container. Please collect and dispose of construction and domestic waste						
	in an acceptable container.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	requested	Latest re	port Date:	12/4/	2019
			<u>.</u>		,	· ·	
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

01/02/20