

City of Albuquerque Stormwater Construction Site Inspection Report

General Information Project Name: Tru by Hilton Location: 4949 Jefferson NE Site Contact Name & Ken Moore, Wright Hospitality [ESC File No. F17E044C Agency ken@wrighthospitality.com NVPBEI No. NMR10021J Inspection Date: 01/09/20 start/End Time! 0955/1015hrs CoA Stormwater Inspector: Timothy E. Sims Construction Phase: vertical vertical Type of Inspection: Regular Storm Event Post Storm Event >0.25" 1311/Complaint x [Follow Up Weather at time of inspection? Clear Temperature: ~ 40* 40* Estimated date of last storm 0.25" or greater 11/27/2019 11/27/2019 Item Deficiency/ Corrective Action Number 1 Track out-pad-requires maintenance 2 2 Perimeter BMP's require maintenance. Please rowide latest SWPP self-inspection. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 12/04/19													
Location: 4949 Jefferson NE Site Contact Name & Ken Moore, Wright Hospitality (ESC File No. F17E044C Agency Ken@wrighthospitality.com [NPPESId. No. NMR10021J Inspection Date: 01/09/20 Start/End Time: 0955/1015hrs CoA Stormwater Inspector: Timothy E. Sims vertical Type of Inspection: Regular Storm Event Post Storm Event >0.25" [311/Complaint] x [Follow Up] Weather at time of inspection? Clear Temperature: ~ 40* Estimated date of last storm 0.25" or greater 11/27/2019 11/27/2019 Item Deficiency/ Corrective Action Number 1 Track-out-pad-requires maintenance. Please re-establish sediment BMP's- 3 Infect production is required for onsite infets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. 2 Perimeter fishe? (V/N) No Integre off site? (V/N)				General I	nformation	l .							
Site Contact Name & Ken Moore, Wright Hospitality [ESC File No. F17E044C Agency Ken Moore, Wright Hospitality (ESC File No. NMR10021J Inspection Date: 01/09/20 Start/End Time: [0955/1015hrs] NMR10021J Construction Phase: vertical vertical Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint] x Follow Up Weather at time of inspection? Clear Temperature: ~ 40* Estimated date of last storm 0.25" or greater 11/27/2019 Item Deficiency/ Corrective Action Number Perimeter BMP's require maintenance. 2 Perimeter BMP's require maintenance. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. 9 Vertarge off site? (V/N) 9 No													
Agency ken@wrighthospitality.com NMPDESId. No. NMR10021J Inspection Date: 01/09/20 [Start/End Time:] 0955/1015hrs Cock Construction Phase: Immety E. Sims vertical Type of Inspection: Regular [Storm Event] Post Storm Event >0.25" [311/Complaint] x [Follow Up Weather at time of inspection? Clear Temperature: ~ 40* Estimated date of last storm 0.25" or greater 11/27/2019 Item Number Deficiency/ Corrective Action 1 Track-out pad requires maintenance 2 2 Perimeter BMP's require maintenance. Please re-establish sediment BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste 1 In an acceptable container. Please collect and dispose of construction and domestic waste <													
Inspection Date: 01/09/20 Start/End Time: 0955/1015hrs CoA Stormwater Inspector: Timothy E. Sims vertical Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x [Follow Up. Weather at time of inspection? Clear Temperature: ~ 40* Estimated date of last storm 0.25" or greater 11/27/2019 Item Deficiency/ Corrective Action Number 2 Perimeter BMP's require maintenance 2 Perimeter BMP's require doe on site inlets. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2 2 2 Discharge off site? (V/N) No	Site Contact Name &		Ken Moore, Wright Hospitality ESC File No.										
CoA Stormwater Inspector: Timothy E. Sims vertical Construction Phase: vertical Yertical Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up Weather at time of inspection? Clear Temperature: 40* Estimated date of last storm 0.25" or greater 11/27/2019 40* Item Deficiency/ Corrective Action Number 2 Perimeter BMP's requires maintenance 2 2 Perimeter BMP's require maintenance. Please re establish sediment BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container.						NMR10021J							
Construction Phase: vertical Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x [Follow Up Weather at time of inspection? Clear Temperature: ~ 40* Estimated date of last storm 0.25" or greater 11/27/2019 Item Deficiency/ Corrective Action Number Perimeter BMP's requires maintenance: 2 Perimeter BMP's require maintenance: 3 Inlet protection is required for onsite inlets: 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2 In an acceptable container. 3 Index protection is required for onside index protection is a compared by the second construction and domestic waste in an acceptable container. 2 In an acceptable container. 3 Index protection is required for onside index protection is required for onside index protection is a compared by the second construction and domestic waste in an acceptable container.													
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up Weather at time of inspection? Clear Temperature: ~ 40* Estimated date of last storm 0.25" or greater 11/27/2019 Item Deficiency/ Corrective Action Number Deficiency/ Corrective Action 1 Track-out-pad requires maintenance 2 Perimeter BMP's require maintenance. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container.			r: Ti	mothy E. Sims									
Weather at time of inspection? Clear Temperature: 40* Estimated date of last storm 0.25" or greater 11/27/2019 40* Item Deficiency/ Corrective Action Number Deficiency/ Corrective Action 1 Track-out-pad requires maintenance 2 2 Perimeter-BMP's require maintenance. Please re-establish sediment-BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container.													
Estimated date of last storm 0.25" or greater 11/27/2019 Item Deficiency/ Corrective Action Number Deficiency/ Corrective Action 1 Track-out pad requires maintenance 2 Perimeter BMP's require maintenance. Please re-establish sediment BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2 Pischarge off site? (Y/N)	Type of inspection: [] Regular [[Storm Event]] Post Storm Event >0.25" [311/Complaint] x [Follow Up												
Estimated date of last storm 0.25" or greater 11/27/2019 Item Deficiency/ Corrective Action Number Deficiency/ Corrective Action 1 Track-out pad requires maintenance 2 Perimeter BMP's require maintenance. Please re-establish sediment BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2 Preserve off site? (Y/N)	Weath	er at time of i	nspection?	Clea	r	Temper	ature: ~ 40*						
Item Number Deficiency/ Corrective Action 1 Track-out-pad-requires maintenance 2 Perimeter BMP's require maintenance. Please re-establish sediment BMP's. 3 Inlet-protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2 Previde acceptable container. 3 Independent of the second container. 4 Styrofoam report is dated 12/04/19 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 4 Integration (see photos) 7 Waste not in acceptable container. 1 Integration (see photos) 1 Integration (see photos) 2 Integration (see photos) 3 Integration (see photos) 4 Integration (see photos)	Estimated	date of last s	storm 0.25" or										
Number Deficiency/ corrective Action 1 Track out pad requires maintenance 2 Perimeter BMP's require maintenance. Please re-establish sediment BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoan rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2				0									
1 Track out pad requires maintenance 2 Perimeter BMP's require maintenance. Please re-establish sediment BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 1			Deficiency/ Corrective Action										
2 Perimeter BMP's require maintenance. Please re-establish sediment BMP's. 3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2	Number												
3 Inlet protection is required for onsite inlets. 4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2 3 4 5 5 6 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 2 3 4 4 5 5 5 6 7 Waste not in acceptable container. 2 3 3 4 4 4 4 4 5 5 6 6 7 <	1												
4 Styrofoam rasping remnants requires mitigation. No BMP installed at time of inspection. This would mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. 1													
mitigate wind blown remnants. 5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container.	-												
5 Several washout on site require mitigation (see photos) 6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container. Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 2 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 1 Image: Container in the last report is dated 12/04/19 2 Image: Container in the last report is dated 12/04/19 2 Image: Container in the last report is dated 12/04/19 2 Image: Container in the last report is dated 12/04/19 2 Image	4												
6 Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19 7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container.													
7 Waste not in acceptable container. Please collect and dispose of construction and domestic waste in an acceptable container.													
in an acceptable container.	6	Please provide latest SWPPP self-inspection report. The last report is dated 12/04/19											
in an acceptable container.													
in an acceptable container.													
2.1 Discharge off site? (Y/N) NO	7			ainer. Please col	lect and disp	ose of construc	tion and domestic waste						
		in an acceptat	ole container.										
4 Self Inspection Reports requested Latest report Date: 12/4/2019	2.1	_		No		<u></u>							
	4	Self Inspect	tion Reports	requested	Latest re	eport Date:	12/4/2019						

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155