

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Tru by Hilton					
Location:		4949 Jefferson NE					
Site Contact Name &		Ken Moore, Wright Hospitality ESC File No. F17E044C					
Agency		ken@wrighthospitality.com NPDES Id. No. NMR10021J					
Inspection				8:25/8:40		1-01-	
CoA Stormwater Inspector: Doug Hughes							
Construction Phase: vertical Type of Inspection: Regular Storm Event Post Storm Event > 0.25" 311/Complaint x Follow Up							
Type of it	ispection: [Kegular	[Storm Event]	Post Storm E	vent >0.25 []	311/Complaint x	rollow up
Weath	er at time of i	nspection?	Cloud	lv I	Tempera	ature: ~	50
Estimated	date of last s	torm 0.25" c	r greater	7 Y	10/4/2019	itare.	30
				The second			
Item			Deficienc	y/ Corrective	e Action		
Number							
1	Remove and properly dispose of all offsite sediment and prevent sediment from leaving the site in the						
_	future.						
2	Direct wash water from stucco, paint and concrete into a leak-proof container or lined pit.						
3	Keep construction and domestic waste in acceptable containers.						
4	Keep construction and domestic waste container lids closed when not in use.						
9							
9							
							-
				100			
			1000000				

						-110-110-1	
		-	1-10-10-				
					51		
							2,000,000
		20.10.00					
*						144.000	

1.1	Discharge off site?	(Y/N)	yes				
5		tion Reports	/	Latest rep	ort Date:	10/9/201	9
٥	Sen mahec	rion vehous	-	Latest leb	ort Date.	10/3/201	
Notes:		4 4 3 4 4	Harman Land and Street			SOUR THE REAL PROPERTY.	
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Doug Hughes (505) 924-3420

jhughes@cabq.gov