

City of Albuquerque Stormwater Construction Site Inspection Report

General Information											
Project Na	20:	Maverik Inc.									
Project Name: Location:		5001 Jefferson									
Site Contact Name &		Will Curly - EB		ESC File No. F17E044C1							
		wcurley@ebnm.com		NPDES Id. No.		NMR1001ZV					
Agency Inspection Date:				945/1000hrs							
CoA Stormwater Inspecto			Timothy E. Sims	043/1000113							
	ction Phase:	vertical									
Type of Inspection: x		Regular Storm Event					Follow Up				
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<u>x</u>	Regular	Storm Event			original and	I ONOW OP				
Weath	er at time of i	nspection?	Clea	ar	Tempe	erature: ~	60*				
Estimated date of last s		torm 0.25" o	or greater			10/4/2019					
Item	Deficiency/ Corrective Action										
Number											
	no issues noted										
	***Please provide latest SWPPP self-inspection report.										
	רובמשב או טאועב ומנכשנ שאירדר שבוו-ווושאבנוטוו ובאטונ.										
							ł				
2.1	Discharge off site?	(Y/N)	No								
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	8/20/20	019				

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155