

City of Albuquerque Stormwater Construction Site Inspection Report

			Genera	I Information			
Project Name:		Montgomery Church of Christ					
Location:			gomery Blvd. NE				
Site Contact Name &		D. Mcall -		ESC File No.		F19E003A	
Agency			sing@comcast			NMR1002FA	
Inspection Date:			Start/End Time:	1200/1230hrs			
	water Inspector	r:	Timothy E. Sims				
	ction Phase:		I I I		tical		T=
Type of In	spection: x	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
Woath.	er at time of i	nspection?		lear	Tomp	erature: ~	44*
Fstimated	date of last s	torm 0.25"	or greater	icai	Тептр	11/22/2019	44
	date of last's	101111 0:25	or greater			11/22/2013	
Item	Deficiency/ Corrective Action						
Number	,,						
1	Chama has sediment in street from the utility crossings for water. Please remove sediment						
	from street.						
2	Coyote pumping not utilizing provided concrete washout facility. Please ensure all concrete						
	washout is cleaned in the provide concrete washout facility.						
3	The storm water quality ponds on the southwest and south east should be constructed at this time						
	to approximately the designed volume to prevent the possibility of illicit discharge from this site.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	S	Latest rep	ort Date:	11/19/	2019
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

01/09/20_____