

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:			3050 Painted Rock						
Location:			3050 Painted Rock						
Site Contact Name &			Robert Schult	is - All-Rite Cons			G10E029D		
Agency					NPDES Id. No.		NMLEWA301		
Inspection Date:				tart/End Time:					
CoA Storm									
Construction Phase:			grading Regular Storm Event Post Storm Event > 0.25" 311/Co					1	
Type of Inspection: x			Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up	
Month	or at time	of i	nanastiana	(IF	Par	Tompo	ratura. ~	6U**	
Weather at time of inspection? Clear Temperature: ~ b Estimated date of last storm 0.25" or greater									
	a dute of last storm 0.25 of greater								
Item	Deficiency/ Corrective Action								
Number									
1	Please provide Stormwater Quality Approval and post in view to the public at site.								
2	Dirt Ramp onto BoB McCannon Parkway requires removal and an acceptable access ramp is								
	required.								
3	Concrete washout not in acceptable container.								
4	Please provide latest SWPPP self-inspection report.								
2.1	Discharge off si	te?	(Y/N)	No					
4	Self Insp	ect	ion Reports	requested	Latest rep	oort Date:	not on	file	
Notes:									

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov