

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	3050 Painted Rock					
Location:		3050 Painted Rock Erin - Westwind Landscape ESC File No. G10E029D					
Site Contact Name &		Erin - Westwin	Erin - Westwind Landscape			G10E029D	
	gency	erin@westw	indlandscaspe		NMR1002VB		
Inspection	Date:	03/25/20 St	art/End Time: 0	930/1000hrs			
CoA Storm	water Inspect	or:			Timothy Sims	5	
Construc	tion Phase:		grading				
Type of Ir	spection:	Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	x Follow Up
Weath	er at time of	inspection?	Cle	ar	Tempe	rature: ~	43*
Estimated date of last storm 0.25" or greater							
Item							
	Deficiency/ Corrective Action						
Number							
	all previous issues mitigated, no new issues observed with this inspection						
2.1	Discharge off site?	? (Y/N)	No				
4	Self Inspe	ction Reports		Latest rep	oort Date:	3/24/2	020
Al . I .							
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

03/25/20