

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information						
Project Name:	DeAnza					
Location:	4301 Central NE					
Site Contact Name & Agency	Adam Romero 440-5277	ESC File No.	G13E032			
	Las Ventanas NM	NPDES Id. No.	NMR10013H			
Inspection Date:	10/08/19	Start/End Time:	2/2:05PM	NMR1000ZW		
CoA Stormwater Inspector:	Doug Hughes					
Construction Phase:	Vertical					
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Cloudy	Temperature: ~	65
Estimated date of last storm 0.25" or greater	10/4/2019		

Item Number	Deficiency/ Corrective Action		
	Reports received and all previous issues mitigated.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 10/7/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Doug Hughes (505) 924-3420  
[jhughes@cabq.gov](mailto:jhughes@cabq.gov)

James D. Hughes