

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Campbell Coumpound						
Location:		Campbell & KaylaLn NW - 2240 Campbell Rd						
Site Contact Name &		T Scott Ashcraft		ESC File No.		G13E032		
Agency		Adam Romero		NPDES Id. No.		NMR1001ZW		
Inspection Date: CoA Stormwater Inspecto				940/0955hrs				
Construction Phase:				Home Construction Post Storm Event >0.25" 311/Complaint Follow Up				
	x	Regular	Storm Event	Post Storm i	event >0.25	311/Complaint	Follow Up	
Weath	or at time of i	nenoction?	Clea	ar	Tompo	rature: ~	82*	
Weather at time of i		storm 0.25" or greater		ai	Tempe	9/14/2019	02	
		101111 0.25				9/14/2019		
Item	Deficiency/ Corrective Action							
Number	Dendency/ corrective Action							
1	Please provide the latests SWPPP self-inspection report.							
2	Washout at the concrete washout facility and 2708 requires mitigation.							
3	Refuse enclosures require maintenance.							
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	tion Reports	-	Latest rep	ort Date:	8/20/20	019	
						; -, -		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155