



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

|   |  |                    |  |               |  |
|---|--|--------------------|--|---------------|--|
| ESC File No.                                  | G15E205                                    | Project Name:      | Black Rock Services Carmony HMA Facility |               |  |
| NPDES Id. No.                                 | NMIR1005DH                                 | Location:          | 706 Carmony                              |               |  |
| 2/1/2023                                      | Owner                                      | Contractor         |  |               |  |
| Operator                                      | Blackrock Services, LLC                    | TLC                |  |               |  |
| Contact name & title                          | Brian Baughman                             | Brian Baugman      |  |               |  |
| e-mail  | brianB@tlcplumbing                         | brianB@tlcplumbing |  |               |  |
| Contact Phone #                               | 382-4570                                   | 382-4570           |  |               |  |
| COA Inspector                                 | Doug Hughes                                | Start/End Time:    | 8AM                                      |               |  |
| Construction Phase:                           | No personel or equipment onsite (inactive) |                    |  |               |  |
| Type of Inspection:                           | Regular                                    | Storm Event        | Post Storm Event >0.25"                  | 311/Complaint |  |
| Weather at time of inspection?                |  | Clear              | Temperature: ~                           | 30            |  |
| Estimated date of last storm 0.25" or greater |  | 12/4/2022          |  |               |  |

| Item Number | Deficiency/ Corrective Action                     |     |                     |  |
|-------------|---|-----|---------------------|--|
| 1           | All previous areas of concern have been mitigated |     |                     |  |
| 2           |   |     |                     |  |
| 3           |   |     |                     |  |
| 4           |   |     |                     |  |
| 5           |   |     |                     |  |
|             |   |     |                     |  |
|             |   |     |                     |  |
|             |   |     |                     |  |
|             |   |     |                     |  |
|             |   |     |                     |  |
| 2.1         | Discharge off site? (Y/N)                         | no  |                     |  |
| 4           | Self Inspection Reports                           | n/a | Latest report Date: |  |

|        |  |
|--------|--|
| Notes: |  |
|        |  |
|        |  |
|        |  |

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Doug Hughes (505) 924-3420  
[jhughes@cabq.gov](mailto:jhughes@cabq.gov)