

City of Albuquerque Stormwater Construction Site Inspection Report

General Information											
ESC File No.			oject Name:	Black	lack Rock Services Carmony HMA Facuility						
NPDES Id. No.			ocation:		706 Carmony						
2/1	/2023	Owner			Contractor						
Operator			Blackrock Services, LLC		TLC						
		Brian Baughman		Brian Baugman							
e-mail		brianB@tlcplumbing			brianB@tlcplumbing						
Contact Phone #		382-4570			382-4570						
COA Inspector		Doug Hughes		Start/End Time	e: 8AM						
Construe	ction Phase:		No pers	sonel or equip	ment onsite	(inactive)					
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up				
Weath	er at time of i		Clea	ar	Tempe	erature: ~	30				
		storm 0.25" or				12/4/2022					
			··								
Item			Deficien	cy/ Correctiv	e Action						
Number				,,							
1	All previous areas of concern have been mitigated										
2											
3											
4											
5											
_											
2.1	Discharge off site?	(Y/N)	no								
4	Self Inspec	tion Reports	n/a	Latest re	port Date:						

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505) 924-3420 jhughes@cabq.gov 2/2/23 James D. Hughes