

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
SC File No.	G19E				Tract 6 & 8 Wymont Subdivision			
PDES Id. No. NMR1						8201 La Morada		
	5/2024	Owner			Contractor			
Operator Contact name & title		Mira Al Sol, LLC Ben Perich						
e-mail		ben.perich@colliers.com						
Contact Phone #		505-507-1678 <sup>1</sup>						
COA Inspector		James Hughes			Time	8:30am		
Construction Phase:		James Hughes				0.50am		
Type of Inspection:		Regular Storm Event Post Storm Ev			grading	311/Complaint Follow Up		
Weather at time of					Temperature: ~ 50			
- vveauii - Stimated	date of last s	storm 0.25" or greater			11/7/2024			
	11/1/2027							
Item		Deficiency/ Corrective Action						
Number								
1	<b>Posting -</b> CGP coverage was not posted so it is visible from the public road nearest to the active part of the							
	construction site, using a font large enough to be readily viewed from a public right-of-way in violation of CGP							
	1.5. <b>Required Mitigation:</b> You must post a sign or other notice of your permit coverage at a safe, publicly							
	accessible location in close proximity to the construction site. The notice must be located so it is visible from							
	the public road that is nearest to the active part of the construction site, and it must use a font large enough to							
	be readily viewed from a public right-of-way per CGP 1.5.							
	be readily vic	ewca nom a p	abile right of w	ay per ear 1.5	·•			
2	<b>SWPPP</b> - The SWPPP wasn't available on-site in violation of CGP 7.3. <b>Required Mitigation:</b> The SWPPP,							
	including the SWPPP Map, Self-Inspection Reports, and Corrective Action Reports, must be kept up-to-date pe							
	CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3 and 7.3. If an on-site location is unavailable to keep the							
	SWPPP when no personnel are present, notice of the plan's location must be posted near the main entrance							
	your construction site CGP 7.3.							
3	BMPs - the new silt fence was cut/broken in the southwest corner of the site (See the attached Photo).							
•	<b>Required mitigation:</b> If at any time you find that a stormwater control needs routine Maintenance, you must							
	immediately initiate the needed maintenance work and complete such work by the close of the next business							
	day. When the problem requires a new or replacement control or significant repair, install the new or modifie							
	control and make it operational or complete the repair by no later than seven (7) calendar days from the time							
	of discovery per CGP 5.2.1.							
•	OI WISCOVERY PER COT 3.2.1.							
4								
2.1	Discharge off site?	(Y/N)	no					
				1 - 1 1	t Data.			
4	Seit inspec	tion Reports	requested	Latest repo	ort Date:	none		
Notes:								
NULES.								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: James Hughes

jhughes@cabq.gov

12/11/2024

James D. Hughes