

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Na	me:	Del Webb at Mirehaven PH 2					
Location:		Tierra Pintada and Mirehaven Arroyo					
Site Contact Name &		Troy Crutchfield		ESC File No.		H09E017F	
Agency		Pulte Home	es	NPDES Id. No.	NMR12AR19		
Inspection Date:		05/17/19	Start/End Time:	1:00/1:50		35-3111-	
CoA Storm	water Inspecto	r:	Curtis Cherne				
	ction Phase:				tical		
Type of I	nspection:	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	X Follow Up
Weath	er at time of i	nspection?	Clear/	Windy	Tempe	rature: ~	70
Estimated date of last storm 0.25" or greater 5/10/2019							
Item			La Company				
The same of the sa			Deficie	ncy/ Correctiv	e Action		
Number							
		· · · · · · · · · · · · · · · · · · ·					
	-						
							·
	 						
						····	
	 						
	ì						
						•	
	+						
			_				
						-	
2.1	Discharge off site?	(Y/N)	no		1.000		
				1 -44	nant Data:	E /1 / /2/	247
4	Seir inspec	tion Reports		Latest rep	ort Date:	5/14/2	J1/
						- America	
Notes:							
All previous issues were addressed							
Mil previous issues were addressed							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cheren PE 505-924-3420

ccherne@cabq.gov

05/17/19 Cuta a Chun