

## City of Albuquerque Stormwater Construction Site Inspection Report

			General	Information	ı		
Project Nar	ne:	Del Webb I	Unit 3				
Location:		Tierra Pintada & Mirehaven Parkway					
Site Contact Name &		Kevin Patton/Brian Anderson ESC File N			H09E017G		
Agency		Pulte Homes NPDES Id. No.			NMR100C1		
Inspection Date:				.00/1145hrs			
CoA Storm	water Inspector	r:	Timothy E. Sims				
	ction Phase:		,	home c	onstruction		
Type of Ir	nspection: x	Regular	Storm Event	Post Storm	n Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~							38*
Estimated date of last storm 0.25" or greater 11/27/2							
Item							
	Deficiency/ Corrective Action						
Number							
1	provide cut backs behind curbs at cut drive pads						
2	Mitigate all domestic and construction waste not in acceptable containers.						
3	concrete washout facility is nearing maintenance requirement.						
3	concrete washout facility is freating maintenance requirement.						
			<u> </u>				
2.1	Discharge off site?	(Y/N)	No	1 - 1 - 1 - 1		42/0/20	04.0
4	Self Inspect	ion Reports	s requested	Latest re	eport Date:	12/9/20	J19
Notes:							
			<del></del>		<del></del>		
					-		-

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

01/08/20\_\_\_\_