

City of Albuquerque Stormwater Construction Site Inspection Report

	General Information									
Project Na	me:	Del Webb Unit 3								
Location:		Tierra Pintada & Mirehaven Parkway								
Site Contact Name &		Kevin Patton		ESC File No.		H09E017G				
Agency		Pulte Homes		NPDES Id. No.	NMR100C1					
Inspection Date:				30/0900hrs						
	CoA Stormwater Inspector: Timothy E. Sims									
	ction Phase:				neter wall and dry utilities					
Type of li	nspection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint x	Follow Up			
Weath	<u>er at time of i</u>	nspection?	Clea	ar		rature: ~	53*			
Estimated	date of last s	storm 0.25" or	greater		4/17/2019					
Item			D (1)							
Number			Deficien	cy/ Correcti	ve Action					
Number										
	Intersection of Echo Canyon and Mirehaven Parkway									
1	dirt ramp requires removal at the end of each day on southwest corner - mitigate									
				,						
	Paved interior	Paved interior roadways/streets								
2	dirt ramp requ	uires removal at	the end of each	day on sout	hwest corner -	mitigate				
	-									
	<u> </u>									
	ł									
	1									
			1	r						
2.1	Discharge off site?	(Y/N)	No							
4	Self Inspec	tion Reports	requested	Latest re	port Date:					
L										

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155