

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:			Del Webb Unit 3				
Location:			Tierra Pintada & Mirehaven Parkway				
Site Contact Name &			Kevin Patton		ESC File No.		H09E017G
Agency			Pulte Homes		NPDES Id. No.		NMR100C1
Inspection Date:			04/25/19 St	art/End Time: 07	30/0745hrs		
CoA Storm	water Insped	tor	r: Ti	mothy E. Sims			
Construc	ction Phase:		perimeter wall and dry utilities				
Type of Inspection:			Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint x Follow Up
Weath	er at time o	of ii	nspection?	Clea	ır	Tempe	erature: ~ 54*
Estimated date of last storm 0.25" or greater 4/17/2019							
Item							
	Deficiency/ Corrective Action						
Number							
	Intersection of Echo Canyon and Mirehaven Parkway						
1	dirt ramp requires removal at the end of each day on southwest corner - mitigate						
т_	an cramp requires removal at the end of each day off southwest corner - midgate						
	Paved interior roadways/streets						
2	dirt ramp requires removal at the end of each day on southwest corner - mitigate						
	,						
2.1	Discharge off site	e?	(Y/N)	No			
4			ion Reports		Latest re	port Date:	
	•		•				
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

<u>tsims@cabq.gov</u> 04/25/19