

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Del Webb Unit 3					
Location:		Tierra Pintada & Mirehaven Parkway					
Site Contact Name &		Kevin Patton/Brian Anderson ESC File No			H09E017G		
		Pulte Homes		NPDES Id. No.		NMR100C1	
Inspection Date:				00/1055hrs			
	water Inspecto	r: Ti	imothy E. Sims				
Construction Phase: perimeter wall and dry utilities							
Type of In	ispection:	Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	x Follow Up
\\/ a a + la .	au at tima a af i	nanastian?	Clavu	al	Topera	matuura. N	CE*
veatne	er at time of i	torm 0.25" or	Cloud	λV	4/22/2019	erature: ~	65*
	date of last's	torni 0.25 or	greater		4/22/2019		
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	No pond NW corner - small unacceptable berm not compactesd						
2			North Street and r				
3	No Inlet protection at storm drains - provide and clean						
4	no pond at storm drain location						
5	require silt fence SE corner of site.						
6	re-establish gravel at staging area within the SE corner.						
			-				
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	reqruested	Latest rep	port Date:		
Notes:	Brian we sch	eduled a follo	w-up on Friday	@ 2:00p.m.			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

05/07/19