

City of Albuquerque Stormwater Construction Site Inspection Report

| General Information | | | | | | | |
|-----------------------|--|---------------------|-------------------|---------------|------------------|---------------|-----------|
| Project Name: | | Del Webb l | Unit 3 | | | | |
| Location: | | Tierra Pintad | da & Mirehaven Pa | arkway | | | |
| Site Contact Name & | | Kevin Pattor | n/Brian Anderson | ESC File No. | | H09E017G | |
| Agency | | Pulte Homes | S | NPDES Id. No. | | NMR100C1 | |
| Inspection Date: | | 10/23/19 | Start/End Time: 0 | 945/1030hrs | | | |
| CoA Storm | water Inspecto | r: | Timothy E. Sims | | | | |
| Construc | ction Phase: | | | perimeter wal | l and dry utilit | ies | |
| Type of Inspection: x | | Regular | Storm Event | | Event >0.25" | 311/Complaint | Follow Up |
| | | | | | | | |
| Weath | er at time of i | nspection? | Cle | ar | Tempe | rature: ~ | 45* |
| Estimated | date of last s | torm 0.25" | or greater | | 10/4/2019 | | |
| Item | | | | | | | |
| | Deficiency/ Corrective Action | | | | | | |
| Number | | | | | | | |
| | no issues observed with this inspection | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 2.1 | Discharge off site? | (Y/N) | No | | | | |
| 4 | Self Inspect | tion Reports | 5 | Latest re | port Date: | 10/21/2 | 019 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Notes: | domestic and construction waste is very well maintained and kept up. | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

 $\label{lem:city} \textbf{City of Albuquerque Stormwater Inspector Signature and date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

10/23/19