

City of Albuquerque Stormwater Construction Site Inspection Report

	THE PARTIES.		General I	nformation			
General Information Project Name: Del Webb at Mirehaven Ph 3,4							
Location:		Tierra Pintada and Mirehaven Parkway					
Site Contact Name &		Brian Anderson ESC File No. H09E017G					
Agency		Pule Homes		NPDES Id. No.	NMR1000C1		
Inspection Date:			Start/End Time:	1:40	2:15		
	vater Inspecto		Curtis Cherne				
	tion Phase:	Infrastructure					
Type of Inspection:		Regular X Storm Event		Post Storm B	st Storm Event >0.25" 311/Complaint X Follow Up		
					~		45
Weath	er at time of	nspection?	nspection? Rain Temperature: ~ form 0.25" or greater				45
Estimated	date of last s	storm U.25	or greater			All the second second second	
Item	Deficiency/ Corrective Action						
Number	Delitation of the state of the						
1	Pond not built at storm drains near Willow Canyon Trl						
2	No gravel at staging area at south end						
	ino graver at staging area at south end						
				·			
					-		
			· <u>-</u>				·
							
_							
			-				
			 				
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspec	tion Reports		Latest rep	ort Date:	3/25/2	2019
		· · · · · · · · · · · · · · · · · · ·					
Notes:							
Met with Brian. Agreed to have mitigation complete by COB Wednesday, 5-15-19							
						**-	
	_ .						
1							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

05/10/19 Center a Chern