NOTE: 2016 Protocol - Maximum of one SSWR per permit

PROPRIETARY COMPANY MATERIAL



Date & Time: 04-23-2020 at 10:45 AM

NATIONAL STORM WATER QUALITY PROGRAM SITE INSPECTION REPORT (SIR)

For use on most PulteGroup Sites as of 01/01/2016

Community Name:		PulteGroup-MS-1026:Mirehaven, 9043 Fenton Lake Road NW, Albuquerque, NM 87120 NPDES: NMR1000C1									
		(Include Site Name, Ci	(Include Site Name, City, State, Zip Code and NPDES/Construction Storm Water Permit Number)								
Master Site List ID:		369	In	Inspection performed by: Mario Alderete, CESSWI CISEC, Green Globe Environmental							
				(Print Na	ame, Company, and Title / Qua	lifications)					
Stages	of Construction:	(check all that apply)	Land Development	Inactive	Vertical Construction	Post-Construction					
			X Land and Vertical								
Type of	Inspection:	(check all that apply)	Routine Inspection Other:	Storm-Event Related	Final Site Inspection						
I.	SWPPP - Respon	d to all Questions									
Item					Yes	No					
A	Was the SWPPP acco	Was the SWPPP accessible at the time of the inspection?			$\overline{\overline{\boxtimes}}$	If "No," then an Action					
В	Is the SSWR correct	ly identified in the SWPPP?				Item is required.					
С	Does the SWPPP reflect the current stage of development?				$\overline{\boxtimes}$	Describe all Action Items					
D	Have all SIR action	Items identified on the precedin	ig reports been resolved?		$\overline{\boxtimes}$	on the reverse side of this sheet. (Section IV)					
E	Is NSQP Signage po	osted and in compliance with N	SQP requirements?		\boxtimes						
II.	Estimated date of	Estimated date of most recent Storm Event That triggered an Inspection: 11-21-2019									
	Provide rainfall information as required by the Applicable Permit: <u>.75 Inches</u> (Base on the storm-event related In Frequency required by the Applica										
III.	Site BMP Inspect	ion	Not								
<u>Item</u>	SWPPP Items		<u>Applicable</u>	<u>Acceptable</u>	Action Item	Assigned To					
Erosion	n Control										
1	Protection of Distur	bed Areas		\boxtimes							
2	Slope Protection			\boxtimes							
3	Vegetation / Revege	etation	\boxtimes								
4	Velocity Reduction Devices / Outlet Protection			\boxtimes							
Sedime	nt Control										
5	Check Dams (rock, §	gravel, other)		\boxtimes							
6	Silt Fence	Silt Fence Berms, Dikes, Straw Wattles									
7	Berms, Dikes, Straw										
8	Detention Basins/Se	ediment Traps		\boxtimes							
9	Stockpiles Protected	d/Stabilized			$\underline{\boxtimes}$						
10	Storm Water Inlet Pr	rotection		$\overline{\boxtimes}$							
Housel	eeping / Trade Con	npliance									
11	Waste and Trash Ma	nagement			\boxtimes						
12	Spill and Leak Prev	ention		\boxtimes							
13	Sanitary Stations			$\underline{\boxtimes}$							
14	Concrete and Const		Ц	Ц	$\underline{\underline{\bowtie}}$						
15		tential Contaminate Storage	Ц								
16	Equipment Storage		Ц	×							
17	Construction Exits	and Entrances		×							
18	Dust Control		H	X	닏						
19	Street Sweeping			$oldsymbol{ol}oldsymbol{oldsymbol{oldsymbol{oldsymbol{oldsymbol{oldsymbol{ol}oldsymbol{oldsymbol{oldsymbol{ol}}}}}}}}}}}}}}}}$	\square						

PROPRIETARY COMPANY MATERIAL

Not											
<u>Item</u>	SWPPP Items (continued)	<u>Applicable</u>	<u>Acceptable</u>	Action Item	<u>Assigne</u>	<u>ed To</u>					
Other	N. 0		₩.								
20	Non-Storm Water Flow										
21 22	Site's Weathering of Storm Events Site Discharge Points	\square	M	H	•						
23	BMP Provider Performance	H	\boxtimes	H							
24	Curb cut back		$\overline{\boxtimes}$								
IV.	Action Items		V. Responsive Action Completion								
Item	Location and Responsive Action to be taken		Date Noted Date of Completion								
	Deficiency Name: Granite mountain										
9	Corrective Action: Need to stabilize dirt piles			04-09-2020							
	Deficiency Name: 2319 komate										
11	Corrective Action: Trash ans stucco washout need to be cleaned	04-09-2020									
	Concerve rection. This is and studed washout need to be created										
	Deficiency Name: 2223 chuckwalla spring										
14	Corrective Action: Concrete washout pool needs to be cleaned	04-09-2020									
	Confective Action. Confecte washout poor needs to be created										
	Deficiency Name: 1904 cebolla creek										
14	Corrective Action: Concrete washout pool needs to be emptied		04-23-2020								
	Confective Action. Concrete washout poor needs to be empired	out									
	Deficiency Name: 9324 wood creek										
14	•		04-23-2020								
	Corrective Action: Concrete washout pool needs to be emptied										
	Deficiency Name: 9209 sugar creek										
24	Corrective Action: Curb cut back		04-23-2020								
	Corrective Action: Curo cut back										
	Deficiency Name: 1804 pebble										
24	Corrective Action: Curb cut back	04-23-2020									
A_{i}	tach additional sheet(s) of SIR addendum if necessary										
	t be reviewed and signed below by SSWR - Not Delegable										
	ion or supervision in accordance with a system designed to as ns who manage the system, or those persons directly responsi										
accurate,	and complete. In the event there are no Action Items in this re	eport that have remaine	ed unresolved for a period in	n excess of that allowed l	by the Applicable Constr	uction General					
	further certify under penalty of law that this Site is in compli- for submitting false information including the possibility of										
	nis report.	ime and imprisonment	ioi kilowilig violatiolis. Ci	ertification applies to the	alea under the supervision	on of the 33 WK					
Certifie	d By: (SSWR - Must be a PulteGroup Employee)		Certified By: (Third Pa	rty Inspector if require	d by the Applicable Per	rmit)					
Cerune	a by. (55 WK Must be a Fulledtoup Employee)			rty inspector ir require	a by the applicable i co	· · · · · · · · · · · · · · · · · · ·					
			Mario Alderete								
Site Sto	rm Water Representative - Print Name and Title	Inspector - Print Name									
			1,	1 ,							
$1/\sqrt{2}$											
			/~10/X10) X	JUMPA							
Site Sta	rm Water Representative Signature (Use Ink)	Date	Inspector Signature (Us	e Ink)		Date					
VI.	Justification for non-completion of Responsive Actions	1	, J (00	,		-					
Describe why any Responsive Actions were not corrected within the permit required time period (if applicable).											
N/A											

 $Attach\ additional\ sheet (s)\ if\ necessary$

Housekeeping / Trade Compliance Deficiency Photos



Deficiency Name: 1904 cebolla creek

Corrective Actions: Concrete washout pool needs to be emptied out

Housekeeping / Trade Compliance Deficiency Photos



Deficiency Name: 9324 wood creek

Corrective Actions: Concrete washout pool needs to be emptied out



Deficiency Name: 9209 sugar creek **Corrective Actions:** Curb cut back



Deficiency Name: 1804 pebble **Corrective Actions:** Curb cut back