

SWPPP COMPLIANCE INSPECTION REPORT

Date of Inspection: 10/5/2023

General Information - Section 1

Operator's Name: McDonald's USA, LLC Conducted By: John Paiz

Project Name: Albuquerque, NM - Unser Blvd & Ladera Dr (30-0236) Title: Inspector **Contact Number:** 5053193085

Project Location: Albuquerque, NM

Type Of Inspection: Weekly

Weather Information - Section 2

Current Weather Conditions: Clear Sky Weather on ground conditions: Dry Has it rained since the last inspection? No

If Yes, what was the estimated total amount of rainfall? Approximately 0.0 inch

| Stage of Construction - Section 3 | | | | | | | |
|-----------------------------------|---------------------|-----------------------|-------|--|--|--|--|
| Stage | Start Date Noted | Completion Date Noted | Notes | | | | |
| BMP Installation | | | | | | | |
| Demolition / Clearing | | | | | | | |
| Grading | | | | | | | |
| Installation of Drainage System | | | | | | | |
| Installation of Utilities | 8/31/2023 | | | | | | |
| Paving | | | | | | | |
| Building Construction | 9/21/2023 | | | | | | |
| Landscaping / Site Stabilization | | | | | | | |
| Permanent BMPs | | | | | | | |

Comments



SWPPP COMPLIANCE INSPECTION REPORT

Operator's Name: McDonald's USA, LLC Conducted By: John Paiz Title: Inspector

Project Name: Albuquerque, NM - Unser Blvd & Ladera Dr (30-0236)

Date: 10/5/2023

Contact Number: 5053193085

| Overall Site Observation - Section 4 | | | | | |
|---|-----|-------|--|--|--|
| Areas Observed | | Notes | | | |
| Are perimeter BMPs adequate? | No | | | | |
| Is inlet protection installed and maintained? | Yes | | | | |
| Do structural BMPs need repair? | No | | | | |
| Are additional structural BMPs needed? | No | | | | |
| Are alternative structural BMPs needed? | No | | | | |
| Do procedural BMPs need to be performed? | No | | | | |
| Are perimeters free of off site tracking? | No | | | | |
| Conditions at outfalls require corrective action? | No | | | | |
| Are natural bodies of water protected? | Yes | | | | |
| Is trash being contained? | No | | | | |
| Does fuel cell have secondary containment? | Yes | | | | |
| Is site free of leaks and spills? | Yes | | | | |
| Are potential pollutants being stored properly? | Yes | | | | |
| Is washout area clearly defined and maintained? | No | | | | |
| Are non-storm water discharges being controlled? | Yes | | | | |
| Are Site Notice(s) posted and legible? | Yes | | | | |
| If SWPPP is on site are all documents present? | Yes | | | | |
| Are changes necessary to the SWPPP? | No | | | | |

Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. I further certify that I am familiar with the Federal Clean Water Act, EPA and state regulations regarding storm water inspections, the regulations themselves, and the SWPPP."

Signature: Title: Inspector

Printed Name: John Paiz Date: 10/5/2023



CORRECTIVE ACTION LOG

Operator's Name: McDonald's USA, LLC Project Name: Albuquerque, NM - Unser Blvd & Ladera Dr (30-0236) Project Location: Albuquerque, NM Type Of Inspection: Weekly

Conducted By: John Paiz

Title: Inspector Contact Number: 5053193085

| Location | Corrective Actions Noted | Date Noted | Verified Repair Date |
|----------------------------------|--|---------------|----------------------------|
| Ladera | Repair or replace damaged silt fence | 10/5/2023 | |
| Main entrance | Street needs to be cleaned due to sediment track out | 10/5/2023 | |
| Northwest perimeter near island | Washout spoils need to be cleaned up off of ground. | 10/5/2023 | |
| Main entrance | Street needs to be cleaned due to sediment track out | 9/28/2023 | |
| Rolloff dumpster | Rolloff dumpster needs to be emptied | 9/28/2023 | 10/5/2023 |
| Stockpile northwest of structure | Washout spoils need to be cleaned up off of ground. | 9/21/2023 | 9/28/2023 |
| Main entrance | Street needs to be cleaned due to sediment track out | 9/14/2023 | 9/21/2023 |
| Perimeter around structure | Washout spoils need to be cleaned up off of ground. | 9/14/2023 | 9/21/2023 |
| Concrete washout | Washout spoils need to be cleaned up off of ground. | 9/7/2023 | 9/14/2023 |
| Notes: Washout spoils have | been cleaned | · | |
| Concrete washout | Washout facility needs to be sealed due to leaking | 9/7/2023 | 9/14/2023 |
| Notes: Washout facility has b | een lined with plastic | , | , |
| Perimeter around structure | Washout spoils need to be cleaned up off of ground | 9/7/2023 | 9/21/2023 |
| Concrete washout | Washout spoils need to be cleaned up off of ground. | 8/31/2023 | 9/14/2023 |
| Notes: Washout spoils have | been cleaned | , | |
| Perimeter around structure | Washout spoils need to be cleaned up off of ground | 8/31/2023 | 9/21/2023 |
| Concrete washout | Washout spoils need to be cleaned up off of ground. | 8/24/2023 | 9/14/2023 |
| Notes: Washout spoils have | been cleaned | ` | ` |
| Northwest corner, near | Washaut spails pood to be alcohold up off of ground | 8/24/2023 | 9/28/2023 |
| structure and stockpile | Washout spoils need to be cleaned up off of ground | 0/24/2023 | 9/20/2023 |
| North corner perimeter | Repair or replace damaged silt fence | 8/18/2023 | 9/21/2023 |
| Concrete washout | Washout spoils need to be cleaned up off of ground. | 8/18/2023 | 9/14/2023 |
| Notes: Washout spoils have | been cleaned | | |