

City of Albuquerque Stormwater Construction Site Inspection Report

roject Nai	me.	Storm Cloud E		formation			
Project Name: Location:		Storm Cloud Estates Tierra Pintada					
Site Contact Name &		Kevin Griffin			022B		
Agency		DR Horton		NPDES Id. No.		NMR10012Y	
Inspection Date:		04/15/19 Sta	art/End Time: 07	30/0900hrs		, v = - ·	
oA Storm	water Inspecto		•		s, Stormwater Inspecto	or	
	ction Phase:						
Type of Ir	nspection:	Regular	Storm Event	Post Storm Ev	vent >0.25" 311/Con	nplaint x Follow Up	
Weath	er at time of i	nspection?	Clea	ir	Temperature: '	~ 53**	
Has th	iere been a st	orm event sin	ce site was Per	mitted?	•		
larify am	ount: (i.e <1	L/4" to >3/4"):	yes, >1/4"				
Item	Item Day 10 March 11 March 12						
Number	Deficiency/ Corrective Action						
	8815 Down Bu	ırst					
1	Other than Lumber debris in front yard- clean and remove to acceptable refuse container.						
2	minor washout on east side of driveway. Mitigate and traing subs about washout preventing						
	future issues.						
	8608 Camino de Venado						
3	re-set and stake portable toilet- staking assists with topledge						
	2100 Roll Cloud Dr						
4	mitigate washout (clean and remove) washout in front yard. It appears sheetrock or paint						
	washout occurred at this location.						
	8604 Down Bu	ırst					
5	re-set and stake portable toilet- staking assists with topledge						
6	Sediment in Streets of subdivision are showing signs of wind blown sediment. Please remove						
	sediment and provide maintenance on drop inlet BMP's.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspec	tion Reports	requested	Latest repo	ort Date:		
		•	'				
	Construction Ge	eneral Permit (CG	D)				
/aintona			e to be comple	tod within co	oven (7) dave		
лаппсепа	nce or correc	live actions ar	e to be comple	teu witiiii se	even (7) days.		
lotes:							
	<u> </u>						

Timothy Sims, 505-803-6155 or

tsims@cabq.gov

Contact information:

04/15/19