

City of Albuquerque Stormwater Construction Site Inspection Report

			General Informa					
Project Name		Ladera Crossing Stif Storage 1911 Cadera Dr Nh						
and L	ocation	1911 Cadera Dr Nh						
Site Conta	act Name & Agency	Arco Mu	HART		ESC File No. NPDES ID No.	1409 E020 NMR 10015F		
Date of In	spection	12-7-18		Start/End 7:30/2:30				
COA Insp	ector Name	Curtis Cherne, Stormwater Quality						
Describe l Phase	Present of Construction	Constructing was bldg , lands caping						
Type of In	nspection: lar • During storm				,	oonse • Follow-Up		
			Weather Informa	tion				
· Cl	\ / '	ain · Sleet ·	Fog · Snowing	-	Tem _j Windy	perature: ~ So F°		
	been a storm event sin							
Amount:	• < 1/4" • 1/4" to 3/4"	· (>¾"	- Snov	v				
			Inspection					
CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required		-1	Location and Notes			
1.5	Post a Notice							
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft							
2.2.3	Sediment control along any perimeter	V	gap in silf fince south edge					
2.2.3	Sediment control along any perimeter	er sit force mandron / replacement ecospology ed						
2.2.3	Sediment control along any perimeter		harrie .		,			
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter				×			
2.2.4	Minimize sediment track-							

2.2.5	Manage stockpiles		
2.2.6	Minimize Dust		
2.2.10	Protect Storm Drain Inlets		
2.2.10	Protect Storm Drain Inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.3.1	Equipment and Vehicle Fueling		
2.3.2	Equipment and Vehicle Washing		
2.3.3	Building Material Storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and Domestic Wastes	V	litter in parking area
2.3.3	Construction and Domestic Wastes		
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	wash-out sw parks Island
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	/	washout south partial of site No washout facility
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	No washout facility
2.4	Dewatering		
2.1	Discharge off site?	· Yes · (No)	
4	Self-Inspection Reports	request	Latest Report Date: 9-25-18 12 book
	ty Inspector Use) Items in	n compliance car	be left blank.

COMPET MCCION	Comercia L'erinde (C	G1)	
Maintenance o	r corrective actions	s are to be completed	l within 7 days.

Notes:	7	days	may	extur	a Cv	yo h	dus	fur	landsarping

City of Albuquerque Stormwater Inspector Signature and Date: Lutt & Inspector Signature Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov