

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	H10E033		Project Name:	2200 Vista Oriente NW			
NPDES Id. No.	NMR10036M		ocation:		2200 Vista Oriente NW		
8/19/2021		Owner			Contractor		
Operator		Tuan Huynh					
Contact name & title		Tuan Huynh					
e-mail		tuanvhnm@yahoo.com					
Contact Phone #		505-269-1418					
COA Inspector		Doug Hughes			Start/End Time	me: 11am	
	ction Phase:				nstruction		
	nspection:	Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
	er at time of i				Temperature: ~ 89		
Estimated date of last storm 0.25" or greater 7/31/2021							
Item							
	Deficiency/ Corrective Action						
Number							
1	Weeds shoult not be any taller or wider than 4". Trim or pull weeds.						
2	The SWPPP must be up-to-date and available onsite.						
3	The Silt Fence needs minor repairs.						
4	NPDES Posting was missing.						
5	Stabilize the site per CGP 2.2.14						
		•					
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspec	tion Reports	Requested	Latest re	oort Date:	7/8/20)21

Notes:Silt Fence needs minor repair, No sign of Stabilization per CGP 2.2.14,The site is inactive and covered with tumble weeds that exceed the maximum 4" width and4" Height allowed by ordinance § 9-8-4 GROWTH OR ACCUMULATION OF WEEDS AND LITTER

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505-803-6155) jhughes@cabq.gov (

8/23/2021

James D. Hughes