

## City of Albuquerque Stormwater Construction Site Inspection Report

			General II	ntormation				
ESC File No.	H10E033 Project Name:				2200 Vista Oriente NW			
NPDES Id. No. NMR10		036M Location:			2200 Vista Oriente NW			
8/3	0/2021	Owner			Contractor			
Operator		Tuan Huynh						
Contact name & title		Tuan Huynh						
e-mail		tuanvhnm@yahoo.com 505-269-1418						
Contact Phone #						1		
COA Inspector		Doug Hughes			Start/End Time: 2pm			
Construction Phase:					struction	lace to the	T- 11	
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weather at time of i					Temperature: ~ 93			
Estimated date of last storm 0.25" or greater 7/31/2021								
Item Number	Deficiency/ Corrective Action							
1	Sign is Posted, SF repaired, report received							
2								
3								
4								
5								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	received	Latest rei	oort Date:	8/30/20	)21	
<u>'</u>	Jen mapee	tion reports	10001100	<u> Latest le</u>	oore Bate.	0,00,20		
Notes: No sign of Stabilization per CGP 2.2.14,								
The site is inactive and covered with tumble weeds that exceed the maximum 4" width and								
4" Height allowed by ordinance § 9-8-4 GROWTH OR ACCUMULATION OF WEEDS AND LITTER								
+ Height allowed by ordinance & 3-0-4 drowth or According to Meeds And Ellier								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-803-6155)

jhughes@cabq.gov

8/30/2021 James D. Hughes