

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	H10E	•			Cactus Patch Plaza		
NPDES Id. No. NMR10		DO433 Location:			7801 La Morado Pl NW		
	9/2021	Owner			Contractor		
Operator		P{acific Cactus, LLC					
Contact name & title		Aaron Carlson					
e-mail		aaron.carlson@yahoo.com					
Contact Phone #		506-6310					
COA Inspector		Doug Hughes			Start/End Time: 11:35 AM		
Construction Phase:					scaping		
Type of Inspection:		Regular	Storm Event	Past Storm I	Event >0.25"	311/Complaint	Follow Up
Weather at time of i		nspection?	clea	r	Temper	ature: ~	89
Estimated	date of last s	torm 0.25" o	r greater			7/31/2021	
Itom							
Item			Deficienc	cy/ Corrective	e Action		
Number							
1	Site looks goo	d					
2							
2							
3							
4							
4							
_							
5							
			_				
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	tion Reports	Requested	Latest rep	oort Date:	N/a	
		•				· · · · · · · · · · · · · · · · · · ·	
Notes: Provide latest self-inspection report.							
Earthwork getting close to 500 cy, G&D Plan required if more than 500 CY							
Earthwork getting close to 500 cy, Gad Plan required it more than 500 CY							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-803-6155)

jhughes@cabq.gov

8/20/2021

James D. Hughes