

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	H10E034		Project Name:	Cactus Patch Plaza			
NPDES Id. No.	NMR100433 L		Location:		7801 La Morado Pl NW		
12/22/2021		Owner			Contractor		
Operator		P{acific Cactus, LLC					
Contact name & title		Aaron Carlson					
e-mail		aaron.carlson@yahoo.com					
Contact Phone #		506-6310					
COA Inspector		Doug Hughes			Start/End Time	Time: 9:45am	
Construction Phase:				Lands	scaping		
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
	Weather at time of i				Temperature: ~ 42		
Estimated date of last storm 0.25" or greater 10/1/2021							
Item							
Number	Deficiency/ Corrective Action						
1	Site looks good						
2							
3							
4							
•							
5							
2.1	Discharge off site?	(Y/N)	no				
4		tion Reports	-	Latest re	port Date:	N/a	
4	Jen inspec	con reports	nequesteu	Latestie	on Date.	iv/a	

Notes:	Provide latest self-inspection report.					
Earthwork getting close to 500 cy, G&D Plan required if more than 500 CY						

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505-803-6155) <u>jhughes@cabq.gov</u> 12/23/21

James D. Hughes