

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	H10E0				Cactus Patch Plaza		
NPDES Id. No. NMR10		05ZF Location:			7801 La Morado Pl NW		
7/25/2024		Owner			Contractor		
Operator		Pacific Cactus, LLC					
Contact name & title		Aaron Carlson					
e-mail		aaron.carlson@yahoo.com					
Contact Phone #		506-6310					
COA Inspector		Chancellor English			Start/End Time: 2:30pm		
Construction Phase:		Stockpiles Regular Storm Event Past Storm Event > 0.25" 311/Complaint Follow U					1
Type of Inspection:		Regular	Storm Event		<u> </u>	311/Complaint	Follow Up
Weather at time of i					Temperature: ~ 75		
Estimated date of last storm 0.25" or greater 6/30/2024							
Item	Definion and Course thing Author						
Number	Deficiency/ Corrective Action						
	CIMPDD. The serve of the CCD is few 2017 in violation of CCD Bort 7.2.11. Beginning desiring the CCD and 1.2.11.						
1	SWPPP - The copy of the CGP is for 2017 in violation of CGP Part 7.2.11. Required mitigation: Once						
	you are authorized for coverage under the 2022 CGP, you must include a copy of the permit in the						
	SWPPP per CGP Part 7.2.11.c.						
2	BMPs - There are missing sections in the perimeter silt fence in violation of CGP Part 2.1.4. Required						
	mitigation: Ensure all stormwater controls are maintained and remain in effective operating condition						
	during permit coverage and are protected from activities that would reduce their effectiveness per						
	CGP Part 2.1.4.						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	ion Reports	yes - QR code	Latest rep	oort Date:	7/5/20	24
NI - I							
Notes:							
SWPPP is in DocBox next to the permit coverage posting.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Chancellor English (505-924-3325)

cenglish@cabq.gov

7/26/2024 Chancellor English