

City of Albuquerque Stormwater Construction Site Inspection Report

			General Information						
Project Name and Location		Sawmill Village Blds A1 4 A2							
		1771 Bellanch							
Site Contact Name & Agency		will coble		ESC File No. NPDES ID No.	H13E0254				
		wm Builders LCC		Start/End ,					
Date of Inspection		12-18-18		Time /0	:35/11:15				
COA Inspector Name		Curtis Cherne, Stormwater Quality							
Describe Present Phase of Construction		Stucco							
Type of In	spection:				11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
• Regul	lar • During storm	event • Post-s	torm event (> 0.25 inch)	311 / Complaint Res	sponse • Follow-Up				
Weather Information									
	Weather at time of this inspection? Clear • Cloudy • Rain • Sleet • Fog • Snowing • Windy Temperature: ~ Y F°								
Has there	been a storm event sine	ce the site was Per	rmitted? Yes · No						
Amount:	• < 1/4" to 3/4"	(>3/3)	• Snow"						
			Inspection						
CGP ¹ Section	BMIP / Activity	Maintenance or Corrective Action Required		Location and Note	S				
1.5	Post a Notice	V	no postin	G					
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft			J					
2.2.3	Sediment control along any peri meter								
2.2.3	Sediment control along any peri meter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.4	Minimi ze sediment track-								

2.2.5	Manage stockpiles		2					
2.2.6	Minimize Dust							
2.2.10	Protect Storm Drain Inlets							
2.2.10	Protect Storm Drain Inlets							
2.2.11	Minimize erosion of conveyance channels							
2.2.12	Sediment Basins							
2.2.14	Stabilize exposed portions of the site.							
2.2.14	Stabilize exposed portions of the site.							
2.2.14	Stabilize exposed portions of the site.							
2.2.14	Stabilize exposed portions of the site.							
2.3.1	Equipment and Vehicle Fueling		¥					
-2.3.2	Equipment and Vehicle Washing	V	no soil Kut unsite					
2.3.3	Building Material Storage							
2.3.3	Fuel. oil, hydraulic fluid, petroleum products and chemical storage	/	trost a deficient Rellomate contains not covered Litter east site. debris					
2.3.3	Construction and Domestic Wastes	/	contains not covered					
2.3.3	Construction and Domestic Wastes	V	littre east site. debris					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	Stuces was -out east sile					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	Concrete wash-out west side					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.							
2.4	Dewatering							
2.1	Discharge off site?	· Yes (No						
4	Self-Inspection Reports	request	Latest Report Date:					
¹ Constru Maintena	ity Inspector Use) Items in action General Permit (Conce or corrective action	CGP)						
Notes:								
, , , , , , , , , , , , , , , , , , ,								
		<u> </u>						
City of Albuquerque Stormwater Inspector Signature and Date: Linta Chun 12-18-10								
Signature Date								

ESC Inspection Form_ November 2018_CGP.docx

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov

23,1