

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	H14E				Agenda Global Warehouse			
NPDES Id. No.	NMR10			1715 5th St NW				
6/13/2023		Owner			Contractor			
Operator		Agenda Real Estate Holdings, LLC			T2 Building LLC			
Contact name & title		Chris Taylor - Partner			Harold Stanley			
e-mail		ctaylor@agenda-global.com			hstanley@HDSTAN.com			
Contact Phone #		505-450-4703			803-8582			
COA Inspector		Chancellor English			Start/End Time	nd Time: 3pm		
Construction Phase:		Construction						
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up								
	er at time of i		Clea	ır	Tempe	rature: ~	80	
Estimated date of last storm 0.25" or greater 5/22/2023								
Item								
	Deficiency/ Corrective Action							
Number								
1	There were no BMPs installed at time of inspection. The ESC Plan shows a silt fence					a silt fence surrou	unding the	
	perimeter. The CGP Section 2.1.4 states that you must ensure all stormwater controls are m				maintained			
	and remain in effective operating condition during permit coverage.							
2	Washout was noted in several areas of the site, but no lined washout container. According to Section						to Section	
2	-							
	2.3.4 of the CGP, you must direct wash water into a leak-proof container or leak-proof and lined pit; do							
	not allow liquid wastes to be disposed of through infiltration or on the ground.							
3	3 The dumpster was not covered at the end of the work-day - contract		 contractors I 	eft during inspect	ion. As per			
	CGP Section 2.3.3.e, provide waste containers of sufficient size and number, and, for the			per, and, for those	e without lids,			
	provide a cover or similarly effective means designed to minimize the discharge of pollutants				nts.			
		,						
4	SWPPP was ur	navailable du	ring time of inspect	ion and an ef	fort to reach o	out to point of co	ntact to locate	
-	SWPPP was unavailable during time of inspection and an effort to reach out to point the SWPPP failed. The SWPPP including Self Inspection Reports and Corrective Action							
			-			•		
	kept up-to-date per CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3 and 7.3. If an on-si							
	unavailable to	keep the SW	PPP when no perso	onnel are pre	sent, notice of	f the plan's location	on must be	
	posted near th	ne main entra	nce of your constru	uction site CG	iP 7.3. Self Ins	spections must als	o continue	
	until NOT is fil	ed and a dete	ermination of stabil	ization is det	ermined by th	e city.		
5 During inspection, in an effort to locate the SWPPP, the phone numbe						or a point of conta	act on the	
_	posting was incorrect. Section 1.5.b requires a contact name and phone number to call for const							
	site information. Update posting with correct contact information.							
				1				
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	no	Latest rep	port Date:			

Notes:	1 violation in 4/22 for out-of-date SWPPP			
2 NOIs - different operator LLCs but same certifier				
Of the 2 points of contact on the posting, 1 has an incorrect phone number, the other is a third				
party, which is not allowed.				

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Chancellor English (505) 924-3325 cenglish@cabq.gov 06/26/2023

Chancellor English