

## City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation				
ESC File No.	H14E			Agenda Global Warehouse				
NPDES Id. No.	NMR10			1715 5th St NW				
6/13/2023		Owner			Contractor			
Operator	-,	Agenda Real Estate Holdings, LLC			T2 Building LLC			
Contact name & title		Chris Taylor - Partner			Harold Stanley			
e-mail		ctaylor@agenda-global.com			hstanley@HDSTAN.com			
Contact Phone #		505-450-4703			803-8582			
COA Inspector		Chancellor English			Start/End Time	Time: 3pm		
Construction Phase:		Construction						
Type of Ir	nspection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
	er at time of i		Clea	ar	Tempe	rature: ~	80	
Estimated date of last storm 0.25" or greater 5/22/2023								
Item								
Number			Deficienc	Deficiency/ Corrective Action				
1	There were no BMPs installed at time of inspection. The ESC Plan shows a silt fence surrounding the							
	perimeter. The CGP Section 2.1.4 states that you must ensure all stormwater contro					ater controls are i	maintained	
	and remain in effective operating condition during permit coverage.							
2	Washout was noted in several areas of the site, but no lined washout container. According to Section							
-	2.3.4 of the CGP, you must direct wash water into a leak-proof container or leak-proof and lined pit; d							
	not allow liquid wastes to be disposed of through infiltration or on the ground.							
3	The dumpster was not covered at the end of the work-day - contractors left during inspection. As per							
	CGP Section 2.3.3.e, provide waste containers of sufficient size and number, and, for th							
	provide a cove	er or similarly	effective means de	esigned to mi	nimize the disc	charge of pollutan	its.	
4	SWPPP was unavailable during time of inspection and an effort to reach out to point of contact to locate							
	the SWPPP failed. The SWPPP including Self Inspection Reports and Corrective Action Reports must be							
			1 and available on-	• •				
		-	PPP when no perso	-				
		•	•	•		•		
	-		ince of your constru			-	o continue	
	until NOT is fil	ed and a dete	ermination of stabil	lization is det	ermined by th	e city.		
<u> </u>								
5	During inspection, in an effort to locate the SWPPP, the phone number for a point of contact on the							
	posting was incorrect. Section 1.5.b requires a contact name and phone number to call for construction							
site information. Update posting with correct contact information.								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	s no	Latest rer	oort Date:			

Notes:	1 violation in 4/22 for out-of-date SWPPP				
2 NOIs - different operator LLCs but same certifier					
Of the 2 points of contact on the posting, 1 has an incorrect phone number, the other is a third					
party, which is not allowed.					

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Chancellor English (505) 924-3325 cenglish@cabq.gov