

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	H14E111		Project Name:		Phoenix Appartments		
NPDES Id. No.			_ocation:		2818 4th St. NW		
8/12/2022		Owner			Contractor		
Operator		Michael Dreskin					
Contact name & title		Michael Dreskin					
e-mail		mdreskin@aol.com					
Contact Phone #		249-7788					
COA Inspector		Doug Hughes			Start/End Time: 11-11:30am		
Construction Phase:					aging		
Type of In		Regular	Storm Event			311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~ 80							
Estimated date of last storm 0.25" or greater 8/1/2022							
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	The SWPPP wasn't available at the time of inspection. The 2017 permit coverage expired and EPA						
1	· · · · · · · · · · · · · · · · · · ·						
	records show it wasn't extended. Self Inspection Reports weren't available. CGP 4 The up-to-date SWPPP						
	must be available onsite CGP 7.1 and new permit coverage must be obtained.						
2	Silt Fence wasn't properly installed. BMPs must be reset within 7 working days CGP 5.2.1						
3	Concrete washout was on the ground. Direct wash water from concrete, paint, and stucco into a leak-						
	proof container per CGP 2.3.4. Remove and dispose of hardened concrete with other waste per CGP						
	2.2.3.						
	2.2.3.						
4							
				T			
2.1	Discharge off site? (Y/N)		no				
4	Self Inspection Reports		required	Latest re	port Date:	none	3
Notes:							
Building Co	onstruction v	vas vertical b	ut no occupancy	yet.			
1 11							

City of Albuquerque Stormwater Inspector Signature and date: 8/15/2022

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov

James D. Hughes