

City of Albuquerque Stormwater Construction Site Inspection Report

ESC File No. H15E007 Project Name: Galles Chevrolet Parking Lot NPDES Id. No. NMR1005MK/NMR1006CY Location: 2001 and 2007 Candelaria Rd. NE		
NPDES Id. No. NMR1005MK/NMR1006CY Location: 2001 and 2007 Candelaria Rd. NE		
8/19/2024 Lessee Lessor		
- P-0.000	SAI Inc.	
Contract Harris of this	Raul Modi	
	saiinc1@yahoo.com	
	505-803-6544	
COA Inspector Chancellor English Start/End Time: 12:30pm		
Construction Phase: Bare dirt no construction activity at 2007 Candelaria		
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up		
Weather at time of inspection? Clear Temperature: ~ 98		
Estimated date of last storm 0.25" or greater 7/27/2024		
Item Deficiency / Converting Action		
Number Deficiency/ Corrective Action		
1 SWPPP and self-inspection reports were unavailable on-site in violation of City Ordinance § 1	14-5-2-	
11(C)(1). Required mitigation : The SWPPP, including the SWPPP Map, Self Inspection Reports		
Corrective Action Reports, must be kept up-to-date per CGP 7.1 and available on-site per CGP	4.7.3,	
5.4.3 and 7.3. Your SWPPP, corrective action log, site inspection, and any other compliance		
documentation required under this permit must be signed by the same responsible corporate	e officer	
who signs the certification statement on your NOI or by a duly authorized representative of the	hat	
person per CGP Appendix G.11.2. Per City Ordinance § 14-5-2-11(C)(1), self-inspections must of	continue	
until the site is "determined as stabilized by the city." The property owner/operator is respons		
determining when the "Conditions for Terminating CGP Coverage" per CGP Part 8.2 are satisfi		
then for filing their Notice of Termination (NOT) with the EPA. Each operator may terminate C		
coverage only if one or more of the conditions in Part 8.2.1, 8.2.2, or 8.2.3 have occurred. After	er filing	
the NOT with the EPA, the property owner is responsible for requesting a Determination of		
Stabilization from the City. Email a copy of the latest self-inspection report to show compliance	ce with	
	ce with	
the CGP and City Ordinance.		
2 BMPs - The silt fence (SF) was missing and/or not embedded around most of the site with sed	liment	
discharging downslope in violation of CGP 2.2.3. Required Mitigation: You must Install sedim	, , , <u> </u>	
controls along any perimeter areas of the site that are downslope from any exposed soil or ot		
disturbed areas, as required by CGP 2.2.3. When the problem requires a new or replacement	control	
or significant repair, install the new or modified control and make it operational or complete i	it by no	
later than seven (7) calendar days from discovery per CGP 5.2.1.		
3 Stabilization - The site is missing temporary or permanent stabilization in violation of CGP Par	rt 2.2.14	
Required mitigation: Initiate the installation of stabilization measures immediately in any area		
exposed soil where construction activities have permanently ceased or will be temporarily ina	active for	
14 or more calendar days and complete the installation of stabilization measures as soon as		
practicable, but no later than 14 calendar days per CGP Part 2.2.14.		
2.1 Discharge off site? (Y/N) no		
4 Self Inspection Reports missing Latest report Date: ???		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: 08/20/2024

Contact information: Chancellor English 505-924-3325

cenglish@cabq.gov

