

GENERAL NOTES

- A. COORDINATE WORK WITH ARCHITECT'S PLANS.
- B. IT IS THE CONTRACTOR'S RESPONSIBILITY TO FIELD VERIFY EXISTING CONDITIONS PRIOR TO CONSTRUCTION. REPORT ALL DISCREPANCIES TO THE ARCHITECT / ENGINEER AND VERIFY THE ARCHITECT / ENGINEER'S INTENT BEFORE PROCEEDING.
- C. ALL TRASH, DEBRIS, & SURFACE VEGETATION SHALL BE CLEARED AND LEGALLY DISPOSED OF OFFSITE.
- D. ALL SUBGRADE, OVEREXCAVATION, AND FILL SHALL BE PLACED AND / OR COMPACTED PER THE GEOTECHNICAL REPORT.
- E. EXCAVATION IS UNCLASSIFIED AND INCLUDES EXCAVATION TO SUBGRADE ELEVATIONS INDICATED BY GEOTECHNICAL REPORT, REGARDLESS OF CHARACTER OF MATERIALS ENCOUNTERED.
- F. PROPOSED SPOT AND CONTOUR ELEVATIONS SHOWN REPRESENT TOP OF FINISH MATERIAL (I.E. TOP OF CONCRETE, TOP OF CONCRETE, TOP OF PAVEMENT MATERIAL, TOP OF LANDSCAPING MATERIAL, ETC.). CONTRACTOR SHALL GRADE, COMPACT SUBGRADE AND DETERMINE EARTHWORK ESTIMATES BASED ON ELEVATIONS SHOWN MINUS FINISH MATERIAL THICKNESSES.
- G. IF FIELD GRADE ADJUSTMENTS ARE REQUIRED, THE CONTRACTOR SHALL NOTIFY THE ARCHITECT/ENGINEER.
- H. UNIFORMLY GRADE AREAS WITHIN LIMITS OF GRADING AS SHOWN ON PLAN. COMPACT WITH UNIFORM SLOPES BETWEEN POINTS WHERE ELEVATIONS ARE INDICATED.
- MAXIMUM SLOPES SHALL BE 3:1. MINIMUM SLOPES SHALL BE 1% UNLESS OTHERWISE NOTED.
- EXISTING UTILITY LINES ARE SHOWN IN AN APPROXIMATE MANNER ONLY AND MAY BE INCOMPLETE OR OBSOLETE. SUCH LINES MAY OR MAY NOT EXIST WHERE SHOWN OR NOT SHOWN. CONTRACTOR SHALL CONTACT NM-811 FOR UTILITY LINE SPOTS TWO WORKING DAYS PRIOR TO CONDUCTING SITE FIELD WORK. CONTRACTOR SHALL FIELD VERIFY AND LOCATE ALL UTILITIES PRIOR TO COMMENCEMENT OF ANY CONSTRUCTION. CONTRACTOR IS FULLY RESPONSIBLE FOR ANY AND ALL DAMAGE CAUSED BY ITS FAILURE TO LOCATE, IDENTIFY AND PRESERVE ANY AND ALL EXISTING UTILITIES, PIPELINES, AND UNDERGROUND UTILITY LINES.
- K. OWNER WILL PROVIDE SOIL TESTING AND INSPECTION SERVICES DURING EARTHWORK OPERATIONS. CONTRACTOR SHALL ALLOW TESTING LABS TO INSPECT AND APPROVE COMPACTED SUBGRADES AND FILL LAYERS BEFORE FURTHER CONSTRUCTION WORK IS DONE. SHOULD COMPACTION TESTS INDICATE INADEQUATE DENSITY, CONTRACTOR SHALL PROVIDE ADDITIONAL COMPACTION AND TESTING AT THE CONTRACTOR'S SOLE EXPENSE.
- L. ADJUST RIMS OF EXISTING UTILITY FEATURES AS NECESSARY TO MATCH NEW GRADES.
- M. UTILITIES IN PAVED AREAS SHALL BE HS-25 TRAFFIC RATED.
- N. ALL NEW PAVEMENT SURFACES SHALL BE CONSTRUCTED WITH POSITIVE SLOPE AWAY FROM BUILDINGS AND POSITIVE SLOPE

TOWARD EXISTING AND/OR PROPOSED DRAINAGE PATHS.

- O. WHERE GRADES BETWEEN NEW AND EXISTING ARE SHOWN AS 'MATCH' OR '±', TRANSITIONS SHALL BE SMOOTH.
- P. ALL FRACTURED FACE ROCK (F.F. ROCK) TO BE 6" AVG. DIA. ANGULAR FACED ROCK PLACED OVER GEOTEX 501 NON-WOVEN GEOTEXTILE (O.E.). NOTE: PERMANENT TUPF REINFORCEMENT MATERIAL (LANDLOK TRM 450 O.E.) MAY BE SUBSTITUTED AT ALL AREAS REFERENCING F.F. ROCK EROSION PROTECTION.
- Q. SIDESLOPES STEEPER THAN 5:1 SHALL HAVE PERMANENT EROSION CONTROL (F.F. ROCK OR LANDLOK TRM 450 O.E.) INSTALLED, TYPICAL.
- R. ALL AREAS DISTURBED BY CONSTRUCTION (OUTSIDE PROPOSED TURF AREA) SHALL BE RESEEDED WITH NATIVE GRASS PER C.O.A. SPECIFICATIONS SECTION 1012 (FOR SANDY SOILS) OR AS SPECIFIED ON THE LANDSCAPE PLAN.
- S. POND DESIGN PARAMETERS (TOP OF POND, BOTTOM OF POND. SIZE OF ORIFICE, AREA OF POND, ETC.) TO BE STRICTLY ADHERED TO FOR CERTIFICATION PURPOSES. SEE DETAIL SHEET FOR ADDITIONAL INFORMATION.

ASSESSMENT/REMEDIATION NOTES

NORTH SIDE OF BUILDING

THE ORIGINAL GRADING PLAN (2002) DID NOT INDICATE A SIDEWALK TO THE EAST OF THE BUILDING DOORWAY. THE SIDEWALK IS INSTALLED HIGHER THAN THE GRADE AT THE BUILDING, SO WATER FROM THE THREE ROOF DRAINS IS TRAPPED BETWEEN THE BUILDING AND THE SIDEWALK.

SITE REMEDIATION:

INSTALL 12" SIDEWALK DRAINS AT ROOF DRAIN LOCATIONS (2) TOTAL) AND INSTALL AN IMPERMEABLE LINER IN LANDSCAPE AREAS. TO CAPTURE WATER DURING SNOWMELT AND MINIMIZE ICE FORMING ON SIDEWALK AND PAVEMENT, SIDEWALK DRAIN OUTLETS SHALL CONNECT TO A NEW 8" STORM DRAIN MAIN EXTENDING TO A NEW BUBBLE UP INLET IN THE NORTHWEST MEDIAN. DURING LARGER STORM EVENTS, THE WATER NOT CAPTURED BY THE SIDEWALK DRAIN DOWN PIPES WOULD CONTINUE TO BE DIRECTED TO THE NORTH PARKING LOT THROUGH THE SIDEWALK DRAIN CURB OPENING AND OVER THE SIDEWALK.

EAST SIDE OF BUILDING

THE ORIGINAL GRADING PLAN SHOWED A SWALE FROM THE SOUTHEAST BUILDING CORNER TO A CURB OPENING EAST OF THE NORTHEAST BUILDING CORNER. THE AS-BUILT GRADE AT THE CURB OPENING IS HIGHER THAN WHAT WAS SHOWN ON ORIGINAL GRADING PLAN SO THE SWALE DOES NOT FUNCTION. CURRENTLY, WATER IS BEING PONDED ADJACENT TO THE BUILDING.

SITE REMEDIATION:

REGRADE THIS AREA TO ESTABLISH POSITIVE DRAINAGE AWAY FROM THE BUILDING AND GRADE A WATER HARVESTING BASIN WITH A PERCOLATION PIT AND SURFACE OVERFLOW TO THE EXISTING CURB OPENING.

SOUTH SIDE OF BUILDING

THE GRADES AT THE SOUTHEAST CORNER OF THE SITE ARE HIGHER THAN THE BUILDING. THERE ARE TWO ROOF DRAINS AT THE SOUTH SIDE OF THE BUILDING WHERE THE SOIL HAS ERODED SIGNIFICANTLY.

SITE REMEDIATION:

REGRADE THE AREA ADJACENT TO THE SOUTHEAST BUILDING CORNER TO ELIMINATE THE EXISTING POND, INLET AND DRAINAGE PIPE TO DIRECT TO THE LARGER PROPOSED WATER HARVESTING BASIN AT THE EAST SIDE OF THE BUILDING. FILL AND COMPACT THE ERODED AREAS BY THE ROOF DRAINS. INSTALL PCC RUNDOWN ADJACENT TO THE SIDEWALK AND EXTEND RUNDOWN TO THE BUILDING AT THE ROOF DRAINS. FIELD ADJUST EXISTING GRADES BETWEEN CONCRETE APRON AND RUNDOWN TO ENSURE POSITIVE DRAINAGE INTO THE RUNDOWN.

WEST SIDE OF BUILDING

THE GRADES ALONG THE WEST SIDE OF THE BUILDING APPEAR TO HAVE SUFFICIENT SLOPE TO THE WEST. THERE IS A SMALL HOSE BIB IN THE WALL SOUTH OF THE BUILDING ENTRANCE THAT APPEARS TO HAVE LEAKED CAUSING DAMAGE TO THE WALL. ADDITIONAL AREAS OF BUILDING CRACKING AND STAINING WERE OBSERVED.

SITE REMEDIATION:

ASSESS IRRIGATION SYSTEM AND GEOTECH FINDINGS. ASSESS AND CLEAN STORM DRAIN SYSTEM FROM THE INTERIOR COURTYARDS TO THE BUBBLE-UP INLET IN THE MEDIAN NORTHWEST OF THE BUILDING. ASSESS ALL EXTERIOR HOSE

CONTRACTOR SHALL PROVIDE AN ITEMIZED PROPOSAL FOR ALL WORK/REPAIRS REQUIRED PER THE ASSESSMENT.

Τ

VICINITY MAP

Т



LEGAL:

A PORTION OF LOT F2A1D, BROADBENT BUSINESS PARK, ALBUQUERQUE, NEW MEXICO

ADDRESS:

BROADBENT PARKWAY N.E.

SURVEYOR:

ENGINEER:

BENCHMARK:

CITY OF ALBUQUERQUE MONUMENT "9-H15". A STANDARD BRASS TABLET LOCATED ON A MEDIAN 0.24 MILES SOUTHWEST OF THE INTERSECTION OF CANDELARIA AND LOCUST ST. N.E. (NAD 1927/SLD 1929) ELEVATION=5034.93

- AS REQUIRED FOR INSTALLATION OF PIPES AND TRENCH
- INSTALL FITTINGS (TEES, BENDS) AS REQUIRED TO CONNECT
- 4. INSTALL ALL SIDEWALK DRAINS, INLET AND PIPES PER


GENERAL INFORMATION


ALDRICH LAND SURVEYING

ISAACSON & ARFMAN, P.A.

GENERAL CONSTRUCTION NOTES

- SAWCUT, REMOVE & REPLACE PAVING, CURB AND SIDEWALK
- ALL PIPE AND FITTINGS SHALL BE ADS N12WT.
- TO 8" MAIN.
- MANUFACTURER'S SPECIFICATIONS.





consulting engineers, inc.

4700 Lincoln Road NE, Suite 102 Albuquerque, NM 87109

505-344-4080 · 505-343-8759 (fax)

ISAACSON & ARFMAN, P.A.

Consulting Engineering Associates

Wisznia Architecture | Development

800 Common Street, Suite 200

New Orleans, LA 70112 Phone: 504.581.1948 Fax: 504.581.1954

www.wisznia.com

Consultants:


evisions:				
No.	Issued For	Date		
	**			

505-899-4886_505-899-4861(FAX)

STRUCTURAL, SITE WORK, AND INTERIOR / EXTERIOR REPAIRS TO: CHILDREN, YOUTH, & FAMILIES DEPARTMENT OF THE STATE OF N.M. 1031 LAMBERTON PLACE NE ALBUQUERQUE, NM 87107

Sheet Title: **GRADING NOTES** 07905 ÅNW Drawn By: Project No FCA 06.27.14 Checked By: Date:





The state of the s

Wisznia Architecture | Development

800 Common Street, Suite 200 New Orleans, LA 70112 Phone: 504.581.1948 Fax: 504.581.1954 www.wisznia.com




Notes:

Consultants:



Chavez-Grieves
consulting engineers, inc.
4700 Lincoln Road NE, Suite 102 Albuquerque, NM 87109
505-344-4080 · 505-343-8759 (fax)





A L B U Q U E R Q U E , N M 8 7 1 1 3
5 0 5 - 8 9 9 - 4 8 8 6 = 5 0 5 - 8 9 9 - 4 8 6 1 (F A X)

Revisions:

No. Issued For Date

Slope grades changed 10/14/14 to 5:1

Project Title:

STRUCTURAL, SITE WORK, AND

STRUCTURAL, SITE WORK, AND INTERIOR / EXTERIOR REPAIRS TO: CHILDREN, YOUTH, & FAMILIES DEPARTMENT OF THE STATE OF N.M. 1031 LAMBERTON PLACE NE ALBUQUERQUE, NM 87107

Sheet Title:

GRADING PLAN & DETAILS

Drawn By:	ANW	Project No.	0790
Checked By:	FCA	Date:	06.27.1
Seal WILSS	Manage Control		

