

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	H18E				McDonald's 30-0001			
NPDES Id. No.	NMR10	JO5YE Location:			5900 Menaul Blvd NE			
11/8/2023		Owner			Contractor			
Operator		McDonald's USA, LLC						
Contact name & title		Alex Breeden						
e-mail		alex.breeden@us.mcd.com						
Contact Phone #		630-207-0289				-		
COA Inspector		Chancellor English		Start/End Tim	e: 1p	m		
	ction Phase:				emo	<u> </u>		
						Follow Up		
Weather at time of				r	Temperature: ~ 70			
Estimated date of last storm 0.25" or greater 9/14/2023								
Item								
Number	Deficiency/ Corrective Action							
1	Permit coverage posting was missing in violation of CGP Part 1.5. Required mitigation: You must post a							
-	sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity							
the construction site per CGP Part 1.5					, , ,			
2	The SWPPP was unavailable during the inspection in violation of CGP Part 7.3. Required mitigation: You							
	must keep a current copy of your SWPPP at the site or at an easily accessible location so that							
	made available at the time of an on-site inspection per CGP Part 7.3. Since there was no po					osting, there		
	was no contact information to call and locate the SWPPP.						•	
3	There were gaps in the straw wattles around the perimeter of the construction site in violation of CGI						ation of CGP	
_	Part 2.1.3. Required mitigation: You must complete installation of stormwater controls by the time							
	each phase of construction activities has begun per CGP Part 2.1.3.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	No	Latest re	port Date:			

Notes:					
Inspection performed on first day of demo					