

City of Albuquerque Stormwater Construction Site Inspection Report

			General Information			
Project Name and Location		mesa del Rio project				
		840 Mesa del RIO NW				
Site Contact Name & Agency		Bill Reilly Habitat for Humanity		ESC File No. NPDES ID No.	210 E012	
Date of Inspection		2-11-19		Start/End Time	10/9715	
COA Inspector Name		Curtis Cherne, Stormwater Quality				
Describe Present Phase of Construction		5166.11701				
Type of Ir	nspection: lar • During storm	0	storm event (> 0.25 inch)	311 / Complaint R	tesponse • Follow-Up	
1 1 1 1 1 1 1 1 1			Weather Information			
	at time of this inspection		Fog · Snowing (Windy	emperature: ~F°	
	been a storm event sin		rmitted? Yes No	,		
Amount.		0	Inspection			
CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required		Location and No	tes	
1.5	Post a Notice					
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.3	Sediment control along any perimeter					
2.2.4	Minimize sediment track	-				

2.2.5	Manage stockpiles					
2.2.6	Minimize Dust					
2.2.10	Protect Storm Drain Inlets					
2.2.10	Protect Storm Drain Inlets					
2.2.11	Minimize erosion of conveyance channels					
2.2.12	Sediment Basins					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.2.14	Stabilize exposed portions of the site.					
2.3.1	Equipment and Vehicle Fueling					
2.3.2	Equipment and Vehicle Washing		Stabili Fil			
2.3.3	Building Material Storage					
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage					
2.3.3	Construction and Domestic Wastes					
2.3.3	Construction and Domestic Wastes					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.					
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.					
2.4	Dewatering					
2.1	Discharge off site?	· Yes · No				
4	Self-Inspection Reports	tion Reports Latest Report Date:				
Notes: (City Inspector Use) Items in compliance can be left blank. Construction General Permit (CGP) Maintenance or corrective actions are to be completed within 7 days.						
Notes:						
	6					

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov

City of Albuquerque Stormwater Inspector Signature and Date:

ECS File: 510 D012



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information					
Project Name and Location	Mesa bet Riv project 840 Mesa let Room Bill Rully Contact Phone #/					
Site Contact Name & Agency	Habital Ser Verants					
Date of Inspection	4-24-17 Start/End 7:40					
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality					
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One					
Describe Present Phase of Construction	Frank al some orthing					
Type of Inspection: Regular During storm event Post-storm event (> 0.5 inch) 311 / Complaint Response Follow-Up Weather Information						
Weather at time of this inspection? Clear Cloudy Rain Sleet Fog Snowing Findy Has there been a storm event since the site was Permitted? Yes No Amount: Ya" 1/4" to 3/4" > 3/4" Snow"						
Erosion & Sediment Control Inspection						
* Entrance / Track-Out						
* Sediment Controls / Silt Fence, Check Dams, Waddles, etc.						
• Erosion Controls / Mulch, Seed, Cuthack at Cwb						
Housekeeping/Pollutant Controls						
• Debris/Pollutants/Sediment in MS4						
• Notes						
Is site being maintained in compliance with the Drainage Ordinance? Fes No Cunto C May 4-2477						