

General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Company</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event --	Last Precipitation -- 48h Forecast --

Inspection Form Instructions

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information**Inspector's Qualifications**

Trained and work experience - see inspector qualification page in section 2 of the SWPPP.

Type of Inspection:

- ☒ **Regular** ☐ During storm event
☐ Post-storm event

Weather Information**Last Storm Event Information**

For information on the last storm event, see the weather event information at the end of this inspection.

Weather at time of this inspection?

- ☐ Clear ☐ Cloudy ☐ Rain ☐ Sleet
☐ Snowing ☐ High Winds

☒ **Partly Cloudy**

Have any discharges occurred since the last inspection?

☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Are there any discharges at the time of this inspection?

☐ Yes ☒ No

If yes, what did the water look like at the time of the discharge?

Is a rain gauge installed on site?

☐ Yes ☒ No

If yes, where is it located?

Representative weather site is used to measure precipitation.

Has the Rain Event Page been filled out?

☒ Yes ☐ No

Are there SDS sheets on site?

☒ Yes ☐ No

General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Company</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez		
Permit #:		Inspection Frequency:			
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event	Last Precipitation	48h Forecast	
		--	--	--	

If yes, where are they located?

On site Job trailer

If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes.

Date Construction Stopped

Date Construction Resumed

Measures Taken to Stabilize the Site:

Construction Phasing

Verify what stage of construction the project is in, and record dates when activities started and were completed.

Installed BMPs

Started

Started:

1/ 2023

Completed:

Site Clearing and Grading

Completed

Started:

1/2023

Completed:

2/2023

Installing Utilities

Started

Started:

2/2023

Completed:

Building Structure

Started

Started:

2/2023

Completed:

General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Company</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez		
Permit #:		Inspection Frequency:			
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event	Last Precipitation	48h Forecast	
		--	--	--	

Paving and Walks

☒ Started

Started:

Walks 3/2023

Completed:

Final Grading/Stabilize Site

Started:

Completed:

Other

Started:

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Silt fence, concrete washout, dumpster,
portable toilet

Are all of the above controls installed?

☒ Yes☐ No

Do any of the above controls need maintenance?

☒ Yes☐ NoIf any of the controls have not been installed or require maintenance,
please list the control and explain.Repair and replace silt fence along the site
perimeter where needed.

Are the BMPs shown on the map?

☒ Yes☐ No

Were there any changes to the SWPPP?

☒ Yes☐ No

Has the SWPPP been updated?

☐ Yes☒ No

Were the changes to the SWPPP implemented within 7 days?

☒ Yes☐ No

General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Company</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez		
Permit #:		Inspection Frequency:			
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event	Last Precipitation	48h Forecast	
		--	--	--	

List any new BMPs needed:

Silt fence

Notes:

Vertical construction in progress. Sidewalks,
Curb and gutter in progress. See the action
items.**Oversight Issues**

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Implemented?

☐ Yes☐ No☒ N/A

Maintenance Required?

☐ Yes☐ No☒ N/A**2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?**

Implemented?

☒ Yes☐ No☐ N/A

Maintenance Required?

☒ Yes☐ No☐ N/A**3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?**

Implemented?

☒ Yes☐ No☐ N/A

Maintenance Required?

☒ Yes☐ No☐ N/A**4. Are discharge points and receiving waters free of any sediment deposits?**

Implemented?

☒ Yes☐ No☐ N/A

Maintenance Required?

☐ Yes☒ No☐ N/A**5. Are storm drain inlets properly protected?**

Implemented?

☐ Yes☐ No☒ N/A

General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Company</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event --	Last Precipitation -- 48h Forecast --

Maintenance Required?

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?

Maintenance Required?

7. Is trash/litter from work areas collected and placed in dumpsters?

Implemented?

Maintenance Required?

8. Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?

Implemented?

Maintenance Required?

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

Implemented?

Maintenance Required

10. Are materials that are potential storm water contaminants stored inside or under cover?

Implemented?

Maintenance Required?

11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?

Implemented?

Maintenance Required?

12. Has the Site map been updated to reflect current conditions?

General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Company</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez
Permit #:		Inspection Frequency:	
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event --	Last Precipitation -- 48h Forecast --

Implemented?

☒ Yes
☐ No
☐ N/A

Maintenance Required?

☐ Yes
☒ No
☐ N/A

13. Is the NOI posted?

Implemented?

☐ Yes
☒ No
☐ N/A

Maintenance Required?

☒ Yes
☐ No
☐ N/A

14. Were previous corrections made within 7 days of last inspection or before the next storm event?

Implemented?

☒ Yes
☐ No
☐ N/A

Maintenance Required?

☒ Yes
☐ No
☐ N/A

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

☐ Yes
☒ No

Have there been any reportable quantities releases of hazardous materials?

☐ Yes
☒ No

Additional Notes

Silt fence repair and replace is already scheduled. The rock pad needs to be refreshed.

General Permit SWPPP Inspection				
Site Name:	<u>Starbucks Coffee Comapny</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez	
Permit #:		Inspection Frequency:		
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event	Last Precipitation	48h Forecast
		--	--	--

Certification & Signatures

Certification Statement:
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X Marcos Valadez

Date
April 5, 2023 at 9:50:25 AM MDT

Title
Inspector

General Permit SWPPP Inspection				
Site Name:	<u>Starbucks Coffee Comapny</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez	
Permit #:		Inspection Frequency:		
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event --	Last Precipitation --	48h Forecast --

Photos




General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Company</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez		
Permit #:		Inspection Frequency:			
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event	--	Last Precipitation	--
			--		--

Weather History



Precipitation
Recorded



No
Precipitation



Missed or data
unavailable

January

April



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.

General Permit SWPPP Inspection

Site Name:	<u>Starbucks Coffee Comapny</u> <u>1124 59th St NW, Albuquerque, NM 87105</u>	Inspector:	Marcos Valadez		
Permit #:		Inspection Frequency:			
Date of Visit:	Apr 5, 2023, 8:55:57 AM	Last Rain Event	--	Last Precipitation	--
			--		--

Action Items

Title	Inspector	Date	Priority	Location	Description	Status	Closer	Notes	Photos
Silt fence	Marcos Valadez	April 5, 2023	7 Days	North, south and east.	Silt fence needs to be repaired or replaced along the site perimeter where needed.	Open			