

City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation	l				
		017 Pr	oject Name:		Starbucks				
NPDES Id. No.	NMR10056F Location:			1440 Coors Blvd NW					
11/1	7/2022	Owner			Contractor				
Operator		Los Dows, LLC							
Contact nai	me & title	Aurthor J Dow							
e-mail		Dowaj@yahoo.com							
Contact Phone #		350-4477				_			
COA Insp		Doug Hughe	es		Start/End Time:	11:30	AM		
	tion Phase:				ading				
Type of Inspection:		Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up		
Weather at time of inspection? Clear Temperature: ~						45			
Estimated	date of last s	torm 0.25" or	greater		10/16/2022				
Item Number	Deficiency/ Corrective Action								
1	The Property Owner's ESC Plan and NOI were not approved by the City, but an NOI was certified on the EPAs website. The ESC plan was submited to the City for the third review yesterday.								
2	Posting of permit coverage was still missing. Post signage of NOI permit coverage in a location clearly visible to the public CGP1.5.								
3	The up-to-date SWPPP was not available onsite. The SWPPP must include self-inspection reports and an accurate SWPPP map showing current BMPs and current area of disturbance per CGP 7.2.1 and 7.2.4.								
4	BMPs were mi	ssing. Correctiv	e actions are requ	uired within	7 days per CGP 5	5.2.1			
2.1	Discharge off site?	(Y/N)	no						
4	Self Inspect	tion Reports	Requested	Latest re	port Date:	None or	ı file		

N	^	+		•
I۷	u	ιτ	: >	•

The first inspection and Notice of Violation #1 was sent on 10/31/22 for Posting, SWPPP, NOI, BMPs, and sediment in the street south and east of the site. At the second inspection on 11/8/22, the only progress was removing the sediment from the streets. The third inspection and notice of Violation #3 was sent on 11/17/22 for Posting, SWPPP, and BMPs.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov