

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. J20E028 Project Name:				NuVue			
NPDES Id. No. NMR10069N & NMR100692 Location:					1171 Jaffa Rd. NE		
	16/2024	Owner -			Contractor		
Operator		4740 Dillon Drive, LLC			Harrison Construction LLC		
Contact na	me & title	Malik Hasan			Patrick Audenis		
e-mail Contact Phone #		accounts@nuvuepharma.com 919-619-2443			harrisonbuildinginc@hotmail.com 949-278-1727		
COA Inspector		Chancellor English			Start/End Time: 12pm		
	ction Phase:				d, stockpiles		
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint Follo	ow Up
	er at time of i		clea		Tempera		30
Estimated date of last storm 0.25" or greater					8/10/2024		
			9				
Item	Deficiency/ Corrective Action						
Number							
1	1 BMPs - There are multiple holes in the perimeter silt fence which is also not entrenched in violation of CGP Part 2.1.4. Required mitigation: Ensure all stormwater controls are maintained and remain in						
	effective operating condition during permit coverage and are protected from activities that would reduce						
	their effectiveness per CGP Part 2.1.4.						
2	Posting - The r	permit coverage	posting had fade	ed and was i	not legible in viol	ation of CGP Part 1.5.	
_	Required mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly						lv
accessible location in close proximity to the construction site. The notice must be I from the public road that is nearest to the active part of the construction site, and large enough to be readily viewed from a public right-of-way per CGP Part 1.5.						= :	-
3	Stabilization - This site has been inactive for multiple months with no stabilization measures installed in						
	violation of CGP Part 22.14. Required mitigation: Initiate the installation of stabilization measures						
	immediately in any areas of exposed soil where construction activities have permanently ceased or will						
	be temporarily inactive for 14 or more calendar days per CGP Part 2.2.14.						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	ion Reports	ok	Latest re	eport Date:	3/29/2024	
Notes:					•		
The SWPP	PP is in a bucke	et east of the	entrance. SWP	PP was not	inspected due	to homeless activity a	at the
			ection was a per		•		
Bate dulli	is the mapecu	on. The mape	.c.ioii was a pei	ineter che	.CR.		

City of Albuquerque Stormwater Inspector Signature and date: 10/17/2024

Contact information: Chancellor English 505-924-3325

cenglish@cabq.gov

Chancellor English