

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	K08E0	1 ,		Ceja Vista Senior Apartments			
NPDES Id. No. NIVIR10				9800 Dsennis Chavez SW			
	7/2021	Owner SM Quraishi			Contractor		
Operator Contact name & title		SM Quraishi			Shakeel Rizvi Shakeel Rizvi		
e-mail		smquraishi@yahoo.com			shaky1424@yahoo.com		
Contact Phone #		379-6643			315-6563		
COA Inspector					Start/End Time:	3pm	
Construction Phase:		0 0		infrastructu	ire complete	i ·	
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint Follow Up	
	er at time of i	nspection? Cloudy			Temperature: ~ 45		
Estimated date of last storm 0.25" or greater 12/11/2020						12/11/2020	
Item							
	Deficiency/ Corrective Action						
Number							
1	This site has disrupted the drainage pattern into the Citys pond south of this site and will be responsible for repares to the City's pond.						
2	BMPS must be added to the SWPPP Map and in the field around the Work Order area of disturbance.						
3	Silt fence was incomplete on the north side of the site.						
4	Ponds are to be the first item of earthwork construction and should help mitigate potential damage						
	to the City's pond.						
5	Stabelization is required for all areas inactive for 14 days.						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	ion Reports		Latest re	port Date:	2/4/2021	
			•	•	•		
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

2/11/2021

James D. Hughes