

## City of Albuquerque Stormwater Construction Site Inspection Report

	MELLING		General Ir	formation				
ESC File No.	K08E	003 Pi	roject Name:					
NPDES Id. No.	NMR1003H4		cation:	Volcano Rd and 102nd St. NW			,	
	1/2021 Owner				Contractor			
Operator				Shakeel Rizvi				
Contact name & title		S.M. Quraishi			Shakeel Rizvi			
e-mail		smquraishi@yahoo.com			shaky1424@yahoo.com			
Contact Phone #					505-315-6563			
COA Inspector		Thomas Evans			Start/End Time:	10:35 AM-11:40 PM		
Construction Phase:					hwork			
Type of Inspection:		Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	spection? clear			Temperature: ~ 79			
Estimated date of last storm 0.25" or greater 6/28/2021								
Item	Itom							
	Deficiency/ Corrective Action							
Number								
1	SWPPP is not on site. The SWPPP must be kept on site and readily accessible. The location of the							
	SWPPP needs to be identified on the NOI permit coverage posting.							
2	Sediment accumulation in the streets and around the inlets. Sweep trackout and remove sediment							
	daily.							
	,	and place in an	approved					
3	Domestic waste on ground. Remove any construction and domestic waste and place in an a							
	waste container.							
4	Silt fence needs maintenance in various areas. Repair/maintain silt fences.							
<u> </u>								
<u> </u>								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Reports	Received	Latest re	port Date:	6/16/20	021	
· ·					per bater	0, 10, 20		

Notes: Met with Shakeel on site and discussed items to be mitigated. The SWPPP is currently at the office. Inlet protection was installed since last inspection. The road off of Unser Blvd is paved up to the road behind Mister Carwash.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215) tevans@cabq.gov

Thomas Evans 07/06/2021